



2-EDE-329

2-EDE-329 · ST-line 2.5i pHEV 225pk 165kw HF45 aut · 11 August 2026 ·
Zaventem (BE)

Specifications

License Plate Number	2-EDE-329	Fuel Type	Hybrid Gasoline
Manufacturer	FORD	VIN	WF0FXXWPMHPS60034
Model	Kuga	Cylinder Capacity	2.488 ^{cm3}
Model Versions	ST-line 2.5i pHEV 225pk 165kw HF45 aut	Transmission Type	Automatisch geschakelde Transmissie
Body Type	5 door hatchback	First Admission	04-09-2023
Color	Grey	Odometer	53.438 ^{Km}
Paint Type	Metallic	Numer Of Keys	2
Production Year	2023	Interior	Black
KW	112	Number Headrests	5

Images





Accessories

ABS	Electrically adjustable driver's seat
Airbags	
Alloy wheels	Electrically adjustable exterior mirrors
Audio System	Fog lights
Automatic air conditioning	Front & rear parking sensors
Bluetooth car kit	Leather steering wheel
Central door locking	Navigation system
Centre armrest	Rear view camera
Charging cable - 230v	Roller cover / parcel shelf
Cruise control	Seat heating
Electric rear windows	Steering wheel multifunction
Electric windows front	Steeringwheel - Heated
	Windscreen - Heated

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	4 ^{mm}	Goodyear	225 ^{mm}	60 ^{mm}	18 ^{inch}	All Season
Rear Left	5 ^{mm}	Goodyear	225 ^{mm}	60 ^{mm}	18 ^{inch}	All Season
Front Right	4 ^{mm}	Goodyear	225 ^{mm}	60 ^{mm}	18 ^{inch}	All Season
Rear Right	5 ^{mm}	Goodyear	225 ^{mm}	60 ^{mm}	18 ^{inch}	All Season
Spare Tire Type	Compressor					

Damages



Damage Part

Tailgate



Damage Type

Scratch(es)




Repair Type

Spray


Acceptable

No




Damage Part

Bumper – Rear



Damage Type

Scratch(es)




Repair Type

Spray


Acceptable

No



Damage Part

Alloy – Right Rear



Damage Type


Damaged

Repair Type

Acceptable

Acceptable

Yes



Damage Part

Overfender



Damage Type

Small scratch(es)

Repair Type

Acceptable

Acceptable

Yes



Damage Part

Reardoor - Right



Damage Type

Small scratch(es)

Repair Type

Acceptable

Acceptable

Yes



Damage Part

Mirror - Rightside



Damage Type

Scratch(es)

Repair Type

Spray

Acceptable

No



Damage Part

Alloy - Right Front



Damage Type

Damaged

Repair Type

Acceptable

Acceptable

Yes



Damage Part

Bumper - Front



Damage Type

Scratch(es)



Repair Type

Spray

Acceptable

No



Damage Part

Alloy - Left Front



Damage Type

Damaged

Repair Type

Acceptable

Acceptable

Yes



Damage Part
Frontdoor - Left



Damage Type
Small scratch(es)

Repair Type
Acceptable

Acceptable
Yes



Damage Part
Reardoor - Left



Damage Type
Small scratch(es)

Repair Type
Acceptable

Acceptable
Yes



Damage Part
Overfender



Damage Type
Small scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part

spoiler RB

Damage Type

Small scratch(es)

Repair Type

Acceptable

Acceptable

Yes