



ARVAL
BNP PARIBAS GROUP

1YKF518

INSPECTION REPORT

End of contract

GENERAL INFO

File	315967
License plate	1YKF518
Vehicle identification number	W1N2533131F872997
Dossier	2020037096
Make	Mercedes GLC Coupé 200d Bus.So
Mileage	156017
First registration	18/09/2020
client availability date	22/06/2026
inspectionDate	01/07/2026



CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
67	Wing Front Left / Trim / Replace	Y
103	Door Rear Left // Painting	Y
125	Light / Rear Left On Rear Bonnet / Replace	Y
136	Bumper Rear // Polish	Y
174	Light / Rear Right / Replace	Y
186	Wing Rear Right // Polish	Y
196	Door Rear Right // Polish	Y
197	Door Rear Right / Trim / Replace	Y
210	Door Front Right // Smart Repair Small	Y
217	Door Front Right / Trim / Replace	Y
310	Wheel Two Tone Front Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	Y
412	Seat Front Left / Bottom Coating / Replace	Y
569	Dashboard / Steering Wheel / Replace	Y
883	Key Price Range 2 //	N



Damage Pictures



Bumper Rear // Polish-scratch



Light / Rear Left On Rear Bonnet / Replace-scratch



Light / Rear Right / Replace-scratch




Wing Rear Right // Polish-scratch



Wheel Two Tone Rear Right // Repair-scratch



Door Rear Right // Polish-scratch



Door Rear Right / Trim / Replace-scratch




Door Front Right / Trim / Replace-scratch



Wheel Two Tone Front Right // Repair-scratch



Wing Front Left / Trim / Replace-scratch



Wheel Two Tone Front Left // Repair-scratch



Door Rear Left // Painting-scratch



Door Front Right // Smart Repair Small-dent



Dashboard / Steering Wheel / Replace-worn



Seat Front Left / Bottom Coating / Replace-worn