
APPRAISAL REPORT



VEHICLE IDENTIFICATION

Driver name:	ASSE I
Make:	VOLKSWAGEN
Model / version:	GOLF VARIANT VIII
Wine:	WVWZZZCDXRW847358
Plate:	2FEN047
Mileage:	57372
First registration:	12/04/2024
Color:	dolphin grey





ADDITIONAL INFORMATION

Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?

DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✓
Maintenance book	
Number of keys:	2
Original key:	✓

PICTURES

















































WINE INFORMATION

Radio	Radio with navigation system	7 speakers
Bluetooth	Manual transmission	6 reports
Automatic headlights	Material: alloy	Reference letter (J)
Front diameter 16	Rear diameter 16	Front width 7.0
Rear width 7.0	Front diameter 16	Rear diameter 16
Front height 55	Rear height 55	Forward speed index V
Rear speed index V	Front width 205	Rear width 205
Additional heating	Automatic climate control	Front center armrest
Rear center armrest	Chrome interior finish	Essence
999 cm3	1.00 litre	81 kW
110 hp	Euro 6	Metallic varnished
Front disc brakes	Rear disc brakes	Heated left-side mirror

Heated right-side mirror	Electrically folding mirrors	Automatic day/night interior rearview mirror
Height-adjustable front left seat	Height-adjustable front seats	Isofix anchors for front passenger seat
Fabric trim	Front parking assistance	Aide au stationnement arrière
Caméra avant	Caméra arrière de recul	Régulateur automatique de la distance
Affichage lecture des panneaux de signalisation	Carte mains libres	Appel de secours
Lunette arrière teintée foncée	Vitres portes arrière teintées foncées	Vitres de custode teintées foncées
détecteur de pluie essuie-vitre	Attelage avec boule rétractable électrique	Ceintures de sécurité arrière centrale à enrouleur
Témoin d'oubli de ceinture avant	Témoin d'oubli de ceinture arrière	Freinage d'urgence assistée autonome (urbain)
Avertisseur d'angle mort	depuis 02.24	Digital Cockpit Pro
poignées de portes éclairée	antenne AM/FM	Car2X communication
radio digitale (DAB)	services Online	garnissage des portes en tissu/simili-cuir
ceintures de sécurité avant avec prétensionneurs et tensionneur final	éclairage d'ambiance	entretien à intervalle flexible (Long Life)
airbag central entre les sièges av	réservoir à charbon actif (EVAP)	QI6

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	✓	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	✓
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:	0	**Fast charging cables:**	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	3 mm	Nexen	205551691v	Summer	Aluminium	×
Front right	3 mm	Nexen	205551691v	Summer	Aluminium	×
Rear left	3 mm	Nexen	205551691v	Summer	Aluminium	×
Rear right	3 mm	Nexen	205551691v	Summer	Aluminium	×

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
2	Bonnet	
3	Bumper F	
4	Bumper R	

Total: 3


ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
1	Cover insulation		✓	×	×
5	Door RR	Scratch(es)	✓	×	×
6	Outside rear-view mirror housing R	Residue	✓	×	×

Total: 3

DAMAGES DETAILS

2 - Bonnet






3 - Bumper F







4 - Bumper R






1 - Cover insulation - Renta®



5 - Door RR - Scratch(es) - Renta®



6 - Outside rear-view mirror housing R - Residue - Renta®



SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

27/10/2026 13:55

Customer

27/10/2026 13:55

Useless