



Audi A6 (MKL): 2BLF427

Vinnumber:	WAUZZZF21NN020338	Versionname:	A6 Avant Business Attraction 35 2.0TDi 163pk/cv 5p S-Tronic
First Registrationdate:	3/01/2022	Fiscalpower:	
Expertise Mileage:	129290	Power Kw:	120
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:	Diesel		
Maintenance	NOT OK		
Maintenance	depuis 9200 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar removable
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

225/55/18/102 Y				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/55 R 18 102 Y
Tyre size FR				225/55 R 18 102 Y
Tyre size RL				225/55 R 18 102 Y
Tyre size RR				225/55 R 18 102 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Service, Maintenance, Check



Seat cover FL, Worn, Check



Backrest cover FR, Scratch(es), Acceptable



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)



Bonnet, Stone chip(s), Acceptable



Outside rear-view mirror housing L, Scratch(es), Acceptable



Charging cable (normal), Missing, Check



Charging cable (fast), Missing, Check



Boot carpet, Stain, Cleaning



Boot lid covering R, Scratch(es), Smart repair



Interior covering C pillar L, Scratch(es), Acceptable



Luggage compartment cover, Stain, Acceptable



Bumper R, Scratch(es), Acceptable



Wing FR, Scratch(es), Repair and paint (complete)



Alloy rim FR polished, Scratch(es), Acceptable



Kenteken	2BLF427
Merk Model	Audi A6 Avant Business Attraction 35 2.0TDi 163pk/cv 5p S-Tronic
Brandstofsoort	Diesel
Datum deel1	1/3/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
6/15/26	123,456	klein materiaal	
6/15/26	123,456	remschijven en blokken achter	Vervangen
6/15/26	123,456	remschijven en blokken vooraan	Vervangen
1/23/25	88,983	batterij	Vervangen
1/23/25	88,983	klein materiaal	
1/23/25	88,983	luchtfilter	Vervangen
1/23/25	88,983	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
1/23/25	88,983	remvloeistof	Vervangen
1/23/25	88,983	ruitenwisserrubber achter	Vervangen
1/23/25	88,983	ruitenwisserrubber vooraan	Vervangen
1/23/25	88,983	ruitenwisservloeistof	Bijvullen/-laden
12/6/23	59,709	brandstof hoofdfilter	Vervangen
12/6/23	59,709	klein materiaal	Uitvoeren
12/6/23	59,709	luchtfilter interieur	Vervangen
12/6/23	59,709	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
12/6/23	59,709	remblokken achter	Vervangen
12/6/23	59,709	remblokken vooraan	Vervangen
12/6/23	59,709	ruitenwisservloeistof	Bijvullen/-laden
12/6/23	59,709	versnellingsbakolie	Uitvoeren
1/2/23	31,391	klein materiaal	Uitvoeren
1/2/23	31,391	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
1/2/23	31,391	ruitenwisserrubber achter	Vervangen
1/2/23	31,391	ruitenwisserrubber vooraan	Vervangen
8/19/22	20,398	controle niveaus	Uitvoeren
6/17/22	9,911	controle niveaus	Uitvoeren
4/1/22	3,744	controle niveaus	Uitvoeren
4/1/22	3,744	olie bijvullen	Uitvoeren