MACADAM









CITROÃ‹N BERLINGO: FV-830-EK

Vinnumber:	**VR7EFYHWCLN528813**	Versionname:	**CITROÃ‹N BERLINGO Taille M 1000kg BlueHDi 75 S&S BVM Club VU [4P] bvm 5-75CH-5cv (fourgonnettesimple cabine)**
First Registrationdate:	**18/11/2020**	Fiscalpower:	
Expertise Mileage:	**118452**	Power Kw:	**55**
Bodytype:	**Transporter**	Body colour	**White**
Gearbox:	**MAN 5 VIT**	Paint type	**Opaque**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Diesel**	Type of rims (mounted)	**Steel**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**3**		
Number head rests	**3**		
Type of rims (mounted)	**Steel**		
Category	**Light Commercial Vehicle**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**1**	Rear parking sensors	
Windows electric F		Sliding door right-side	
Cruise Control		Seat cover lining	**Lining Other**
Type of climate control	**Manual climate control**		

Tyres

Summer tyres:	**215/65/16/98 H**			
	Fr.L.	**Falken: 0%**	Fr.R.	**Falken: 0%**
	Re.L.	**Falken: 0%**	Re.R.	**Falken: 0%**

Tyre profile depth FL	**8.6**
Tyre profile depth FR	**9.2**
Tyre profile depth RL	**9.0**
Tyre profile depth RR	**9.0**
Tyre size FL	**215/65 R 16 98 H**
Tyre size FR	**215/65 R 16 98 H**
Tyre size RL	**215/65 R 16 98 H**
Tyre size RR	**215/65 R 16 98 H**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**1957074**
Tyre make FR	**1957074**
Tyre make RL	**1957074**
Tyre make RR	**1957074**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**

Inner door sill FL, Scratch(es), Paint




Interior trim, Damaged, Replace




Door FL, Scratch(es), Paint




Bumper F, Scratch(es), Repair and paint (complete)




Bumper F, Unclasped, Dismount/Mount




Door FR, Scratch(es), Paint




Bumper R, Scratch(es), Repair and paint (complete)




Boot door panel RL, Dent(s), Repair and paint (complete)







Boot door panel RR, Dent(s), Acceptable





Bodywork, Glue residues, Acceptable




ALPHABET

Historique Maintenance

Immatriculation: **FV-830-EK** Date de 1ère immatriculation: **18/11/2020**

Modèle: **Citroen BERLINGO Taille M 1000kg BlueHDi 75 S&S BVM Club VU [4P] bvm 5-75CH-5cv (fourgonnettesimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
16/06/2026	114.869	PROTIERE SAVIGNEUX	Main D'œuvre
			RECYCLAGE
			Elément de Contrôle Pollution
			Examens et Diagnostics - Divers
			Réservoir ADBLUE (Remplacement)
			Essai routier
			Eclairage
			Eclairage de plaque d'immatriculation (Remplacement)
			Ampoule de phare (Remplacement)
			Eclairage
			Soufflet de joint homocinétique - Arbre d'entraînement externe (Remplacement)
			Pieces
			Petite Fourniture moteur
			Petite Fourniture moteur
			Arbre d'entraînement (Remplacement)
			Joint de différentiel (Remplacement)
			Petite Fourniture moteur
			Petite Fourniture moteur
			Transmission
			Huile de transmission (Remplacement)
			RESERVOIR ADBLUE RPLT
			RESERVOIR ADBLUE RPLT
			LAMPE AR RPLT
			LAMPES AV RPLT
			SOUFFLET DE CARDAN RPLT
28/10/2024	78.825	ETABLISSEMENTS PROTIERE	AMORTISSEURS AV RPLT
			RECYCLAGE
			REVISION
			BALAIS ESSUIE GLACE AV
			DISQUES PLAQUETTES AR RPLT
			ECLAIRAGE DE PLAQUE RPLT
31/01/2024	53.330	ETABLISSEMENTS PROTIERE	MOTEUR ESSUIE GLACE RPLT

Historique Maintenance

Immatriculation: **FV-830-EK** Date de 1ère immatriculation: **18/11/2020**

Modèle: **Citroen BERLINGO Taille M 1000kg BlueHDi 75 S&S BVM Club VU [4P] bvm 5-75CH-5cv (fourgonnettesimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
			RECYCLAGE
15/09/2023	53.330	ETABLISSEMENTS PROTIERE	BALAIS ESSUIE GLACE AV
			RECYCLAGE
			REVISION
			FILTRE CLIM RPLT
			LIQUIDE DE FREIN
			REVISION
			FILTRE A AIR RPLT
			PLAQUETTES AV RPLT
02/06/2022	30.824	ETABLISSEMENTS PROTIERE	REVISION
			RECYCLAGE
			BALAIS ESSUIE GLACE AV