



BMW 2 Reeks Gran Tourer (UKL): 2BGX537

Vinnumber:	WBA6V710805U56735	Versionname:	218i Gran Tourer (F46) 1.5i 136pk/cv 5p
First Registrationdate:	22/11/2021	Fiscalpower:	
Expertise Mileage:	92383	Power Kw:	100
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:	Petrol		
Maintenance	OK		
Maintenance	+9000 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Type of Tow bar	No Tow bar
GPS			
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

205/60/16/96 W				
Summer tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 7 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				7.0
Tyre profile depth RR				7.0
Tyre size FL				205/60 R 16 96 W
Tyre size FR				205/60 R 16 96 W
Tyre size RL				205/60 R 16 96 W
Tyre size RR				205/60 R 16 96 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Bumper F, Scratch(es), Acceptable



Bumper moulding F, Scratch(es), Acceptable



Windscreen, Scratch(es), Replace



Alloy rim FL, Scratch(es), Acceptable



Door RL, Scratch(es), Acceptable



Wing RL, Dent(s) and scratch(es), Acceptable



Bumper R, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Acceptable



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)





Bodywork, Paint measurement, Acceptable



Kenteken	2BGX537
Merk Model	BMW 218i Gran Tourer (F46) 1.5i 136pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	11/22/21

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
3/12/26	85,451	ruitenwisservloeistof	Bijvullen/-laden
10/24/25	76,806	batterij	Vervangen
10/24/25	76,806	BMW/MINI service standaard omvang	Uitvoeren
10/24/25	76,806	BMW/MINI voertuigcontrole	Uitvoeren
10/24/25	76,806	klein materiaal	
10/24/25	76,806	nazicht technische keuring	Uitvoeren
10/24/25	76,806	remblokken achter	Vervangen
10/24/25	76,806	ruitenwisserrubber achter	Vervangen
10/24/25	76,806	ruitenwisservloeistof	Bijvullen/-laden
10/24/25	76,806	service microfilter	Uitvoeren
10/24/25	76,806	service motorolie	Uitvoeren
1/22/25	62,877	BMW/MINI service standaard omvang	Uitvoeren
1/22/25	62,877	controle niveaus	Uitvoeren
1/22/25	62,877	klein materiaal	
1/22/25	62,877	remblokken vooraan	Vervangen
1/22/25	62,877	remvloeistof	Vervangen
6/12/24	51,964	batterij	Vervangen
6/12/24	51,964	BMW/MINI service standaard omvang	Uitvoeren
6/12/24	51,964	BMW/MINI service voertuig-check	Uitvoeren
6/12/24	51,964	bougie	Vervangen
6/12/24	51,964	klein materiaal	
6/12/24	51,964	service luchtfilter	Uitvoeren
6/12/24	51,964	service microfilter	Uitvoeren
6/12/24	51,964	service motorolie	Uitvoeren
12/22/23	40,335	BMW/MINI service standaard omvang	Uitvoeren
12/22/23	40,335	controle niveaus	Uitvoeren
12/22/23	40,335	klein materiaal	Uitvoeren
12/22/23	40,335	remblokken achter	Vervangen
4/6/23	26,717	batterij	Vervangen
4/6/23	26,717	BMW/MINI service standaard omvang	Uitvoeren
4/6/23	26,717	BMW/MINI voertuigcontrole	Uitvoeren
4/6/23	26,717	klein materiaal	
4/6/23	26,717	service microfilter	Uitvoeren
4/6/23	26,717	service motorolie	Uitvoeren