APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name:	
Make:	RENAULT
Model / version:	CAPTUR
Vin:	VF1RJB00469803672
Plate:	2CSE565
Mileage:	89701
First registration:	08/11/2022
Color:	

ADDITIONAL INFORMATION

Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?

DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✗
Maintenance book:	
Number of keys:	2
Original key:	✓

PICTURES


























VIN INFORMATION

Radio
6 rapports
Poignées de portes ton caisse
Diamètre avant 17
Largeur arrière 7,0
Hauteur avant 60
Indice de vitesse arrière H
Roue de secours tôle plate
Accoudoir central avant
1.00 litre
Euro 6
Rétroviseur intérieur jour/nuit automatique
Aide au stationnement avant
Régulateur et limiteur de vitesse

Lunette arrière teintée foncée
détecteur de pluie essuie-vitre
Airbag rideaux arrière
Protection piéton

depuis 09.22
passage automatique des phares longue portée en feux de croisement (PRAHL)

Radio avec système de navigation
Projecteurs à allumage automatique
Matière : alliage
Diamètre arrière 17
Diamètre avant 17
Hauteur arrière 60
Largeur avant 215
Climatisation automatique
Essence
74 kw
Nacrée vernissée
Siège avant gauche réglable en hauteur

Aide au stationnement arrière
Verrouillage centralisé à commande à distance
Vitres portes arrière teintées foncées
Airbag latéraux avant
Témoin d'oubli de ceinture avant
Assistant maintien de la voie

carrosserie renforcée 03 (CHC03)
feux ar LED (FEUAR4)

Boîte manuelle
Code équipement EA3
Lettre repère (J)
Largeur avant 7,0
Diamètre arrière 17
Indice de vitesse avant H
Largeur arrière 215
Climatisation réfrigérant 1234YF
999 cm3
101 ch
Frein à main électrique
Garnitures tissu et simili-cuir

Caméra arrière de recul
Appel de secours

Vitres de custode teintées foncées
Airbag rideaux avant
Témoin d'oubli de ceinture arrière
Freinage d'urgence assistée autonome (urbain)
antenne en aileron de requin (ANTEN2)
volant en mousse 1 (VLMOU1)

tableau de bord numérique + indicateurs analogiques (MET04) | Eco Mode | Micro Hybrid (HYB01)
Multi-Sence System 1 (MLEXP1/MDMOD) | gestion de la vitesse (AVOSP1) | suspension durcie 1 (TRSEV1)
alarme distance de sécurité (DWGE01) | événement commercial EV4GA1

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	×	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	×
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:	0	**Fast charging cables:**	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	6 mm	Vredestein	215/60/R17/96H	Winter	Aluminium	×
Front right	6 mm	Vredestein	215/60/R17/96H	Winter	Aluminium	×
Rear left	6 mm	Vredestein	215/60/R17/96H	Winter	Aluminium	×
Rear right	6 mm	Vredestein	215/60/R17/96H	Winter	Aluminium	×

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
2	Inner door sill RR covering	Dent(s) and scratch(es)

Total: 1

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
1	Bodywork	Dent(s) and scratch(es)	✓	×	×

Total: 1

DAMAGES DETAILS

2 - Inner door sill RR covering - Dent(s) and scratch(es)



1 - Bodywork - Dent(s) and scratch(es) - Renta®








SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

05/10/2026 12:46