MACADAM









CITROÃ‹N C3 SOCIÃ‰TÃ‰: GB-992-ZZ

Vinnumber:	**VF7SWYHTUMT539930**	Versionname:	**CITROÃ‹N C3 SOCIÃ‰TÃ‰ BlueHDi 100 S&S BVM6 Feel Nav VF [5P] 6-102CH-5cv (bi-corps VU-)**
First Registrationdate:	**27/09/2021**	Fiscalpower:	
Expertise Mileage:	**161482**	Power Kw:	**75**
Bodytype:	**Berline**	Body colour	**White**
Gearbox:	**MAN 6 VIT**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Diesel**	Type of rims (mounted)	**Steel**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**2**		
Number head rests	**2**		
Type of rims (mounted)	**Steel**		
Category	**VS**		

Options

Number of keys total	**1**	Radio	
Number keys remote	**1**	Headlights Xenon/LED/Laser	
GPS big screen color		Rear parking sensors	
Windows electric F		Seat cover lining	**Lining Other**
Cruise Control			
Steering wheel multifunctional			
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**205/55/16/91 H**			
	Fr.L.	**Bridgestone: 45%**	Fr.R.	**Bridgestone: 40%**
	Re.L.	**Michelin: 70%**	Re.R.	**Michelin: 70%**

Tyre profile depth FL	**5.1**
Tyre profile depth FR	**5.7**
Tyre profile depth RL	**3.7**
Tyre profile depth RR	**3.7**
Tyre size FL	**205/55 R 16 91 H**
Tyre size FR	**205/55 R 16 91 H**
Tyre size RL	**205/55 R 16 91 H**
Tyre size RR	**205/55 R 16 91 H**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**255**
Tyre make FR	**255**
Tyre make RL	**261**
Tyre make RR	**261**

Assistance equipment

Remote ignition key, Missing, Repair/replace (lump sum)




Interior, Dirty, Cleaning







Tyre RL, Out of tolerance, Replace




Tyre RR, Out of tolerance, Replace




Door trim FL, Scratch(es), Replace





Door trim RL, Scratch(es), Replace




Bumper moulding FL, Scratch(es), Paint





Bumper moulding F, Scratch(es), Replace





Windscreen, Stone chip(s), Windscreen repair 2 stonechips






Door RR, Dent(s) and scratch(es), Repair and paint (complete)







Side repeater R, Waterinfiltration, Replace







Luggage compartment cover, Missing, Replace




Rear bulkhead lining, Unclasped, Dismount/Mount





Rubber seal for boot lid, Tear, Replace




Boot lid covering R, Scratch(es), Replace








Bumper R, Scratch(es), Paint







Bodywork, Not original part, Sticker removal small





ALPHABET

Historique Maintenance

Immatriculation: **GB-992-ZZ** Date de 1ère immatriculation: **27/09/2021**

Modèle: **Citroen C3 SOCIÉTÉ BlueHDi 100 S&S BVM6 Feel Nav VF [5P] 6-102CH-5cv (bi-corps VU-)**

Date	Kilométrage	Fournisseur	Descriptif
22/05/2026	155.762	LES CHEVRONS SOFIDA LENS LOOS EN GOHEL	INJECTEUR ADBLUE RPLT
			DEMARREUR RPLT
			DIVERS ALIMENTATION
11/03/2026	141.359	LES CHEVRONS SOFIDA LENS LOOS EN GOHEL	TLG POUBELLE
09/03/2026	137.850	LES CHEVRONS SOFIDA	REVISION
			FILTRE A AIR RPLT
			FILTRE CLIM RPLT
			LAMPE RPLT
			BALAIS ESSUIE GLACE AV
			BALAI ESSUIE GLACE AR
			COURROIE ACCESSOIRES RPLT
			DIVERS CLIM
			REVISION
29/01/2026	131.280	FLEET SOLUTIONS FRANCE	REPARATION DE ROUE
07/11/2025	117.710	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
31/10/2025	116.083	EUROFLEET TYRES AND SERVICES	REMPLACEMENT PNEUS 4 SAISONS
27/06/2025	100.153	LES CHEVRONS SOFIDA	LIQUIDE DE FREIN
			DIVERS CLIM
			DISQUES PLAQUETTES AV RPLT
			PLAQUETTES AR RPLT
			FILTRE CLIM RPLT
			REVISION
18/04/2024	59.106	GUEUDET ASTERIA CEOS	RECYCLAGE
			BALAI ESSUIE GLACE AR
			BALAIS ESSUIE GLACE AV
			REVISION
			FILTRE A AIR RPLT
			FILTRE CLIM RPLT
			REVISION
23/02/2023	40.101	GUEUDET ASTERIA CEOS	ADBLUE
			BALAI ESSUIE GLACE AR

Historique Maintenance

Immatriculation: **GB-992-ZZ** Date de 1ère immatriculation: **27/09/2021**

Modèle: **Citroen C3 SOCIÉTÉ BlueHDi 100 S&S BVM6 Feel Nav VF [5P] 6-102CH-5cv (bi-corps VU-)**

Date	Kilométrage	Fournisseur	Descriptif
			BALAIS ESSUIE GLACE AV
			FILTRE CLIM RPLT
			REVISION