

INSPECTION REPORT

End of contract

GENERAL INFO

File	314858
License plate	2AQP313
Vehicle identification number	W0V7H9EB6M4178022
Dossier	2021 021 014
Make	Opel Crossland 1.2 96kW Elegan
Mileage	79736
First registration	14/06/2021
client availability date	15/06/2026
inspectionDate	02/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	



DAMAGES

Damages	Type	Acceptable
83	Door Front Left // Painting	Y
103	Door Rear Left // Painting	Y
137	Bumper Rear // Replace without painting	Y
156	Rear Bonnet // Polish	Y
159	Rear Bonnet / Rear Window / Replace	Y
202	Rocker Panel Right // Painting	Y
213	Door Front Right // Painting	Y
310	Wheel Two Tone Front Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
634	Rear Left Door Interior Coating // Replace Completely	N

Damage Pictures



Rocker Panel Right // Painting-scratch



Door Front Right // Painting-scratch



Wheel Two Tone Front Right // Repair-scratch



Wheel Two Tone Front Left // Repair-scratch



Door Rear Left // Painting-scratch




Bumper Rear // Replace without painting-scratch



Rear Bonnet / Rear Window / Replace-scratch




Wheel Two Tone Rear Right // Repair-scratch



Rear Bonnet // Polish-scratch



Rear Left Door Interior Coating // Replace Completely-scratch



Door Front Left // Painting-bad repair