

MACADAM ITALY S.R.L. Piazza Belgioioso, 2 - 20121 Milano (MI) Tel. - Fax Piva: 12729790969				Report No.		Expert's report for Alphabet Italia				Type of insurance Perizia				
				Policyholder				Opposite party				Opposite party company		
				Operation 2026		Claim number		Code / Agency				Date accident 01/07/2026		
				Expert code		Adjuster code		Policy number		Injured person can recover the VAT				
Date assignment 01/07/2026		Date first survey 10/07/2026		Place Salerno		C/O	Repairs		Photo	Lien in favor of		Expiry date		
Ownership certificate Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN)											Formerly plate			
Lessee / Co-owner											Date of overhaul			
Vehicle (Brand - Model - Version) AUDI Q8 50 TDI 210kW quattro tip.							Plate GF157BZ		Vin Chassis WAUZZZF12MD033370		First Registration 29/03/2021			
Usage status NON CONOSCIUTO		Km 70119	Tyres % 60	Color Nero		Type of enamel METALLIZED/DOUBLE			Consistency of damage		Type of Expert's report NOT DEFINITIVE			
Equipment														
Approval code		For commercial vehicles	Carrying Qls 0	Tare, Q 0	Wheelbase	Seats No. 0	Axles 0							
Commercial value (C)		Wrecked car value		Value by difference		Ancillary expenses								
Damaged items / restoration operations						SR		LA		VE		ME	D.M. S.C.	Costs of spare parts * (VAT excluded)
						Dif	Time	Dif	Time	Dif	Time	Time		
1	4M8833051C	Rear door		L	S		S		S					
1	4M8853969AGRU	Trim of rear door		L	S		S		S					
1	4M8949101	Fanalino lat. retrovisore est.		L	S		S		S					
1	4M8857409AF9B9	External electrically adjustable rear-view mirror		L	S		S		S					
1	4M8853703AT94	Door compartment structure trim		L	S		S		S					
1	4M8807065AGRU	Front bumper			L		L		L					
1	4M8857528GRU	External rear-view mirror cap		R	L		L		L					
1	4M8833052C	Rear door		R	L		L		L					
1	Codice Ricambio	Paraurti post (completo)			L									
1	4M8857527GRU	External rear-view mirror cap		L	L		L		L					
1	Codice Ricambio	Smacchiatura Interni												
1	Codice Ricambio	Proiettore ant. - lucidatura		R										
1	Codice Ricambio	Ripristino n. 04 dischi in lega da 22												
1	Codice Ricambio	Pneumatico ant e post dx 285/40R22												
1	Codice Ricambio	Volante - PRM												

New for old value (N)	Remarks Pneum. Good Year 285/40 R22. Vhl sporco. Manutenzione scaduta.
-----------------------	--

ALPHABET

Telaio WAUZZZF12MD033370

GF157BZ

AUDI Q8 50 TDI 210kW quattro tip. Sport sports utility vehicle 286CV 5P automatico

Current Odo (Time of Ma	Maintenance Request	Service Type Descriptio	Maintenance Job Description
26.213	23/06/22	Maintenance	Pasticche freni anteriori
26.213	23/06/22	Maintenance	Pasticche freni posteriori
26.213	23/06/22	Maintenance	Spazzole tergi anteriori
26.213	23/06/22	Maintenance	Spazzole tergi posteriori
26.213	23/06/22	Tagliando a 30 000 km	Tagliando a 30 000 km
28.538	11/08/22	Maintenance	Batteria
28.587	12/08/22	Maintenance	Additivo FAP
34.184	13/12/22	Maintenance	Livelli
34.184	13/12/22	Maintenance	Sonda lambda
40.249	26/06/23	Tagliando a 45 000 km	Tagliando a 45 000 km
40.250	26/06/23	Maintenance	Rigenerazione FAP
49.694	03/06/24	Tagliando a 50 000 km	***Service at 50 000 km
50.503	24/06/24	Maintenance	Gestione Garanzia
55.169	15/11/24	Maintenance	Additivo FAP
55.169	15/11/24	Maintenance	Livelli
57.574	04/02/25	Maintenance	Generico

ALPHABET

57.574	04/02/25	Maintenance	Serbatoio carburante
57.574	04/02/25	Maintenance	Sonda lambda
59.973	15/04/25	Maintenance	C/A Valvola EGR
59.973	15/04/25	Maintenance	Rigenerazione FAP
60.268	12/06/25	Maintenance	Pasticche freni posteriori
60.268	12/06/25	Tagliando a 60 000 km	Tagliando a 60 000 km
60.608	18/04/25	Maintenance	Revisione Periodica MTC
60.608	18/04/25	Maintenance	Revisione Periodica MTC mo
68.588	22/04/26	Maintenance	Additivo FAP
68.588	22/04/26	Maintenance	Generico
68.588	22/04/26	Maintenance	Sonda lambda