



PEUGEOT 308 3

-	
VIN	VR3F3DGXTPY681650
Première immatriculation	28/12/2023

DÉTAILS DE L'INSPECTION

Date de l'inspection	05/03/2026 12:28:33	Adresse d'inspection	
----------------------	---------------------	----------------------	--

INFORMATIONS SUR LE VÉHICULE

VIN	VR3F3DGXTPY681650	Transmission	Avant
Type de carrosserie	Berline	Nbre sièges	5
Nbre portes	5	Nombre appuis-têtes	5
Première immatriculation	28/12/2023	Couleur intérieur	Noir
Type de carburant	Hybride rechargeable	Couleur carrosserie	Gris
Marque	PEUGEOT	Catégorie	Vehicule particulier
Modèle	308 3	Couleur tableau de bord	Noir
Boîte de vitesses	Automatique		

DOCUMENTS ET CLÉS


Carnet d'entretien	Oui	Certificat immatriculation (original)	Original
Nbre clés total	2	Certificat immatriculation (original)	Oui
Nbre clés télécommandes	2	Entretien	Non
Manuel d'utilisation	Oui		

OPTIONS

Camera de recul	Oui	Nature de peinture	Metallisé
-----------------	-----	--------------------	-----------

DAMAGES

Interior



1 | Service

Damage type	Missing
Repair mode	Execute



15 | Luggage compartment cover

Damage type	Burned
Repair mode	Replace

Exterior



2 | Alloy rim FL bitone/polychrome

Damage type	Scratch(es)
Repair mode	Repair/replace (lump sum)





3 | Alloy rim RL bitone/polychrome

Damage type	Scratch(es)
Repair mode	Acceptable



4 | Alloy rim RR bitone/polychrome

Damage type	Scratch(es)
Repair mode	Acceptable



5 | Alloy rim FR bitone/polychrome

Damage type	Scratch(es)
Repair mode	Repair/replace (lump sum)





6 | Wing FL

Damage type	Dent(s)
Repair mode	Repair and paint (complete)



7 | Door FL

Damage type	Dent(s)
Repair mode	Repair and paint (complete)



8 | Bumper F

Damage type	Scratch(es)
Repair mode	Paint



9 | Wing RR

Damage type	Scratch(es)
Repair mode	Paint



10 | Door RR

Damage type	Scratch(es)
Repair mode	Paint



11 | Door FR

Damage type	Scratch(es)
Repair mode	Paint



12 | Outer sill R

Damage type	Scratch(es)
Repair mode	Polish



13 | Side repeater R

Damage type	Broken
Repair mode	Replace



14 | Wing FR

Damage type	Scratch(es)
Repair mode	Paint



16 | Bumper R

Damage type	Scratch(es)
Repair mode	Paint



17 | Bumper spoiler Rear

Damage type	Scratch(es)
Repair mode	Acceptable



18 | Roof

Damage type	Dent(s)
Repair mode	Repair and paint (complete)



Commercial photos

