ARVAL
BNP PARIBAS GROUP

2DHQ579

INSPECTION REPORT

End of contract

GENERAL INFO

File	323963
License plate	2DHQ579
Vehicle identification number	VXKUPHMHDN4422063
Dossier	2023 031 018
Make	Opel Corsa 1.2 75 Edition 5d/p
Mileage	44349
First registration	22/03/2023
client availability date	07/10/2026
inspectionDate	09/10/2026











CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	




B
2 - DHQ - 579
KEURING

DAMAGES

Damages	Type	Acceptable
891	Lettering Removal 15min	N
12	Bumper Front // Smart Repair Large	Y
181	Wing Rear Right // Smart Repair Medium	Y
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N

Damage Pictures




Bumper Front // Smart Repair Large-scratch




Wing Rear Right // Smart Repair Medium-scratch




Wheel Alloy Front Right // Repair-scratch




Wheel Alloy Rear Right // Repair-scratch + dent








Lettering Removal 15min-