

2-FAW-653

2-FAW-653 · TS 1.8 Hybrid Dynamic + Business pack · 30 June 2026 ·
Zaventem (BE)

Specifications

License Plate Number	2-FAW-653	Fuel Type	Hybrid Gasoline
Manufacturer	TOYOTA	VIN	SB1ZB3AE80E096206
Model	Corolla	Cylinder Capacity	1.798 ^{cm³}
Model Versions	TS 1.8 Hybrid Dynamic + Business pack	Transmission Type	Automatisch geschakelde Transmissie
Body Type	5 door hatchback	First Admission	11-03-2024
Color	Silver	Odometer	53.595 ^{Km}
Paint Type	Metallic	Numer Of Keys	2
Production Year	2024	Interior	Grey
KW	72	Number Headrests	5

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Fog lights

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance 21-08-2025

Last maintenance odometer 33.866

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	4 ^{mm}	Semperit	205 ^{mm}	55 ^{mm}	16 ^{inch}	All Season
Rear Left	5 ^{mm}	Semperit	205 ^{mm}	55 ^{mm}	16 ^{inch}	All Season
Front Right	4 ^{mm}	Semperit	205 ^{mm}	55 ^{mm}	16 ^{inch}	All Season
Rear Right	5 ^{mm}	Semperit	205 ^{mm}	55 ^{mm}	16 ^{inch}	All Season
Spare Tire Type	Compressor					

Damages



Damage Part

Damage Type

Repair Type

Acceptable

Skirt - Left

Scratch(es)

Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Frontdoor - Left

Door-edge chipped

Acceptable

Yes



Damage Part

Damage Type

Repair Type

Acceptable

Mirror - leftside

Scratch(es)

Spray

No



Damage Part
Alloy - Left Front

Damage Type
Damaged

Repair Type
Rim repair

Acceptable
No



Damage Part
Hood

Damage Type
Stonechipping

Repair Type
Acceptable

Acceptable
Yes



Damage Part
Bumper - Front

Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part	Damage Type	Repair Type	Acceptable
Alloy - Right Front	Damaged	Rim repair	No



Damage Part	Damage Type	Repair Type	Acceptable
Alloy - Right Rear	Damaged	Rim repair	No



Damage Part	Damage Type	Repair Type	Acceptable
Skirt - Right	Scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Reardoor - Right	Small dent(s)	Restyle	No



Damage Part
Bumper - Rear

Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part
spoiler RB

Damage Type
Broken

Notes
Sierlijst

Repair Type
Replace

Acceptable
No




Damage Part
Tailgate

Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part	Damage Type	Repair Type	Acceptable
Interior	Stains & dirt	Cleaning	No