



Expertise

Protocol number: 46413241  
Order No. / Reference: 26584114  
Inspection date: 9 Jul 2026

Manufacturer: Ford

Model: S-Max 2.0 EcoBlue Aut. TREND

VIN: WF0JXXWPCJLS19463



| Vehicle details                         |                       |
|-----------------------------------------|-----------------------|
| Manufacturer / Type / Model / Equipment |                       |
| Ford S-Max 2.0 EcoBlue Aut. TREND       |                       |
| Vehicle Identification number           | WF0JXXWPCJLS19463     |
| Mileage (Read)                          | 158,462 km            |
| First registration                      | 16 Feb 2021           |
| Number of holders                       | 1                     |
| Next periodical technical inspection    | 02/2028               |
| (Report on hand)                        |                       |
| Power / Engine displacement             | 110 kw / 1,995 ccm    |
| Fuel type / Cylinder                    | Diesel / 4            |
| Gearbox / Number of gears               | Automatic / 8         |
| Type of drive                           | Front drive           |
| Type of vehicle                         | Van                   |
| Colour / colour code                    | Polar Silber-Metallic |
| Doors / Seats                           | 5 / 5                 |
| Upholstery type                         | Cloth                 |
| Colour of upholstery                    | Anthracite-Black      |



| Vehicle details                              |                              |                         |                                                            |
|----------------------------------------------|------------------------------|-------------------------|------------------------------------------------------------|
| Maintenance booklet / proof                  | digital proof / complete     | Next maintenance in     | 7 Monat(e)                                                 |
| Last service on / at                         | 02/2026 at 159,672 km        |                         |                                                            |
| Key is / should be                           | 2 / 2                        | FZG documents           | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
|                                              |                              | Letter No.              | FZ433701                                                   |
| Previous damage / Accident                   | Detectable                   | Repainting              | None detectable                                            |
| Inspection conditions                        | sufficient                   | Lifting equipment / pit | No                                                         |
| Test drive                                   | Not performed                | Engine function test    | Performed                                                  |
| Manufacturer key number/<br>type code number | 8566 / BKM 00927             |                         |                                                            |
| Emission standard                            | EURO6;WLTP;AP;PI/CI; M, N1 I | fine dust sticker       |                                                            |
| Permitted total weight                       | 2,555 kg                     | Empty weight            |                                                            |

| Tyres            |                 |                             |                             |             |
|------------------|-----------------|-----------------------------|-----------------------------|-------------|
| Mounted tyres    |                 |                             |                             |             |
| #                | Tyre size       | Type of tyre                | Manufacturer                | Tread depth |
| 1)               | 235/55 R17 103Y | Summer tyres on Light alloy | Dunlop                      | 6mm / 6mm   |
| 2)               | 235/55 R17 103Y | Summer tyres on Light alloy | Dunlop                      | 6mm / 6mm   |
| Additional tyres |                 |                             |                             |             |
| #                | Tyre size       | Type of tyre                | Manufacturer                | Tread depth |
| 1)               | 235/55 R17 103V | Winter tyres on Light alloy | Bridgestone                 | 4mm / 4mm   |
| 2)               | 235/55 R17 103V | Winter tyres on Light alloy | unterschiedliche Hersteller | 7mm / 6mm   |
| Replacement      |                 |                             |                             |             |
| Typ              | Tyre size       | Type of tyre                | Manufacturer                | Tread depth |
|                  | Tirefit         | Expiration date 12/2024     |                             |             |

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

## Equipment

### Standard equipment

- Storage compartments
- Exterior mirrors in body color, driver and passenger side, electrically adjustable and heated
- Hill start assist
- roof console
- Tachometer
- Driver information system display 10.7cm color
- High Beam Assist
- Ford Easy Fuel
- Ford Power Start function
- luggage compartment cover
- Cruise control system with intelligent speed limiter
- Back window, heater
- Interior lighting with delay circuit
- Intelligent security system
- Electric child safety lock
- Steering wheel: Steering column, adjustable in height and reach
- Front center console with padded armrest
- Fog light
- Front and rear parking pilot system
- Tire repair kit
- LED taillights
- Headlight dipped beam with switch-off delay including "greeting function"
- Seats: Driver and passenger seats, 4-way manually adjustable
- Start-stop system
- Bumpers painted in body color
- Daytime running light
- Traffic sign recognition system
- Warning system for unfastened seat belts for the 1st and 2nd rows of seats
- Anti-lock braking system (ABS)
- Attachment points for safety partition grilles
- Tires: 7.5 J x 17 alloy wheels (4) with 235/55 R 17 tires
- third brake light
- Diesel particulate filter (DPF)
- Electronic Shifter
- Electric windows front and rear
- Electronic parking brake
- Ford EasyFold: 2nd row seat backrests fold down electrically at the touch of a button.
- Luggage compartment lighting
- Transmission: 8-speed automatic transmission
- rear window wiper
- Interior mirror, automatically dimming
- Isofix bracket
- Air conditioning with automatic temperature control
- Steering wheel: Multifunction leather steering wheel
- Reading lights front and rear
- MyKey key system (individually programmable second key)
- Emergency brake light
- Upholstery: Cloth
- Tire Pressure Monitoring System (TMPS)
- Windscreen wipers with rain sensor
- Headlight assistant with day/night sensor
- Electromechanical power steering
- Seats: Flexible seating system "FoldFlatSystem (FFS)"
- Seats: Front sports seats
- Power outlet: 12-volt connection in the luggage compartment and in the center console
- Premium carpet floor mats, front and rear
- Lashing eyes in the luggage compartment
- Immobiliser
- Central locking with remote control

### Extra equipment

- Paint finish: Metallic
- Package: Family (Sunshade blinds integrated into the rear side doors - Trays on the front seat backrests - 230-volt socket - Cigarette lighter and ashtray in the center console)
- Package: Winter (Heated windscreen - Heated leather steering wheel - Individually and variably heated front seats)
- Side windows from the 2nd row of seats and rear window, dark tinted.
- Package: Business I (Ford navigation system incl. Ford SYNC 3, AppLink, 20.3 cm touchscreen, DAB/DAB+, voice control, support for Android Auto and Apple CarPlay, Bluetooth hands-free system and audio streaming, FordPass Connect, eCall emergency call system, live traffic information, Wi-Fi hotspot, radio/CD player, 2 USB ports, 8 speakers, steering wheel controls, LED daytime running lights, park assist with automatic parallel and perpendicular parking function, pre-collision assist, forward collision warning, active emergency braking, reversing camera)



## Brief expert findings

|                      |                                                                                                                                                                                                                                               |
|----------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Documents submitted  | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)                                                                  |
| VIN comparison       | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.                                                                     |
| Inspection           | The inspection conditions were sufficient for the assessment of the vehicle.<br>No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent. |
| Test drive           | No test drive/shunting maneuver was carried out during the inspection of the vehicle.                                                                                                                                                         |
| Engine function test | An engine test run was performed.                                                                                                                                                                                                             |

## Value reducing factors

| No. | Component group              | Description                                            |
|-----|------------------------------|--------------------------------------------------------|
| 1   | Equipment                    | Tirefit filler - Expired - Replace                     |
| 2   | Trim / covers                | Boot lid - interior trim - Scratch(es) - Loss in value |
| 3   | Side panel - rear right side | Sill - Dent / paintcoat damage - Smart repair          |
| 4   | Mudguard - left side         | Mudguard - left side - Stone chips - Smart repair      |
| 5   | Bonnet                       | Bonnet - Stone chips - Smart repair                    |

## Previous damages

| No. | Previous damage                                            | Extent of damage (Net) |
|-----|------------------------------------------------------------|------------------------|
| 1   | Side - left, Provided by user / customer, from 11 Jan 2026 | 1.659,82 €             |

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features  
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.  
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

## Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten möglich.



**Figure 1:** Diagonal front (left)



**Figure 2:** Diagonal front (right)



**Figure 3:** Diagonal rear (left)



**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents



Figure 16: Documents



Figure 17: Documents



Figure 18: Additional tyres



Figure 19: Navigation



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.





Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace



Damage 2: Trim / covers: Boot lid - interior trim - Scratch(es) - Loss in value



**Damage 2:** Trim / covers: Boot lid - interior trim - Scratch(es) - Loss in value




**Damage 2:** Trim / covers: Boot lid - interior trim - Scratch(es) - Loss in value



**Damage 3:** Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



**Damage 3:** Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair




**Damage 4:** Mudguard - left side: Mudguard - left side - Stone chips - Smart repair



**Damage 4:** Mudguard - left side: Mudguard - left side - Stone chips - Smart repair



**Damage 5:** Bonnet: Bonnet - Stone chips - Smart repair



**Damage 5:** Bonnet: Bonnet - Stone chips - Smart repair



# Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF0JXXWPCJLS19463  
Hersteller / Modell: FORD FORD S-Max 2.0 EcoBlue Aut. TREND

| Datum      | KM-Stand | Beschreibung                                                                                                                                                                                                                                                                |
|------------|----------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 05.02.2026 | 159.672  | AU; Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges                                        |
| 20.05.2025 | 127.259  | Luftfiltereinsatz ern; Reparatur Sonstiges; Systemtest/Eigendiagnose                                                                                                                                                                                                        |
| 19.02.2025 | 119.934  | Bremsflüssigkeit; Bremsflüssigkeit ern; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/Eigendiagnose; Wartung Sonstiges                                                                                     |
| 14.03.2024 | 89.366   | AU; Bremsklötze hinten; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges                                                                                                                                                                            |
| 01.12.2023 | 80.744   | Batterie ern; Reparatur Sonstiges; Wartung Sonstiges                                                                                                                                                                                                                        |
| 27.05.2023 | 65.403   | Getriebeöl ern/prüfen; Systemtest/Eigendiagnose; Wartung Sonstiges                                                                                                                                                                                                          |
| 30.03.2023 | 59.688   | Reparatur Sonstiges; Wartung Sonstiges                                                                                                                                                                                                                                      |
| 01.03.2023 | 59.680   | Bremse Sonstiges; Bremsflüssigkeit; Bremsflüssigkeit ern; Bremsklötze vorne; Bremsscheiben + Klötze v; Bremsscheiben vorne; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/Eigendiagnose; Wartung Sonstiges |