



FORD Puma 1.0 EcoBoost 125cv ST-Line MHEV todoterreno 92kW 5P manual: 1196-MYL

Vinnumber:	WF02XXERK2RK05724	Versionname:	
First Registrationdate:	14/02/2025	Fiscalpower:	0
Expertise Mileage:	16827	Power Kw:	
Bodytype:	SUV	Body colour	White
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:			
Fueltype:	Hybrid		
Engine functioning	Yes		
Battery functioning	Yes		
Vehicle running	Yes		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	No		
Category	Passenger Car		
Registration Certificate Car (BE)	No		

Options


Number of keys total	1	Central consol F
Number keys remote	1	Luggage cover
GPS big screen color		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Steering wheel leather		
Radio multimedia		
Type of climate control	Autom climate control	

Tyres

	215/55/17/98 W			
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				215/55 R 17 98 W
Tyre size FR				215/55 R 17 98 W
Tyre size RL				215/55 R 17 98 W
Tyre size RR				215/55 R 17 98 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

User's manual, Missing, Repair/replace (lump sum)



Service book, Missing, Repair/replace (lump sum)




MOT certificate, Missing, Repair/replace (lump sum)



Registration document, Missing, Repair/replace (lump sum)



Ignition key, Missing, Repair/replace (lump sum)



Interior, Dirty, Cleaning



Rear light L, Broken, Replace



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Tailgate / Boot, Dent(s) and scratch(es), Replace and paint



Rear light L tailgate, Broken, Replace



Rear window, Missing, Replace



Number plate light L, Broken, Replace



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)



Tyres, No damage, Check

