


2-EWU-620 · Move! 1.0 TSI 110cv DSG bicolor · 28 July 2026 · Zaventem (BE)

Specifications

License Plate Number	2-EWU-620	Fuel Type	Gasoline
Manufacturer	SEAT	VIN	VSSZZZKJ2RR084532
Model	Arona	Cylinder Capacity	999 ^{cm3}
Model Versions	Move! 1.0 TSI 110cv DSG bicolor	Transmission Type	Automatisch geschakelde Transmissie
Body Type	5 door hatchback	First Admission	22-02-2024
Color	Black	Odometer	73.277 ^{Km}
Paint Type	Metallic	Numer Of Keys	2
Production Year	2024	Interior	Grey
KW	81	Number Headrests	5

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Seat heating

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	2 ^{mm}	Hankook	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Rear Left	4 ^{mm}	Hankook	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Front Right	2 ^{mm}	Hankook	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Rear Right	4 ^{mm}	Hankook	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Spare Tire Type	Compressor					

Damages



Damage Part

Interior



Damage Type


Stains & dirt

Repair Type

Cleaning


Acceptable

No



Damage Part

Alloy – Right Front



Damage Type

Damaged

Repair Type

Acceptable


Acceptable

Yes



Damage Part

Fender – Front Left



Damage Type

Dent(s)

Repair Type

Panelbeating &
Spray

Acceptable

No



Damage Part

Damage Type

Notes

Repair Type

Acceptable

Frontdoor - Left

Small scratch(es)

Deurgreep

Acceptable

Yes



Damage Part

Damage Type

Repair Type

Acceptable

Fender - Rear Left

Small dent(s)

Acceptable

Yes



Damage Part

Damage Type

Repair Type

Acceptable

Tailgate

Small scratch(es)

Acceptable

Yes



Damage Part

Trunkshelf



Damage Type

Missing

Repair Type

Replace

Acceptable

No