



PEUGEOT 5008: GF-019-DR

Vinnumber:	VF3MCYHZMNS029283	Versionname:	PEUGEOT 5008 BlueHDi 130 S&S Allure Pack VP [5P] bvm 6-130CH-7cv (SUV)
First Registrationdate:	11/03/2022	Fiscalpower:	
Expertise Mileage:	92858	Power Kw:	96
Bodytype:	SUV	Body colour:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Tow bar	
Number keys remote	2	Radio	
GPS big screen color		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Headlights Xenon/LED/Laser	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Steering wheel leather		Roof bar black	
Type of climate control	Autom climate control	Rear view camera	
		Seat cover lining	Lining Other
			Lining Leather

Tyres

	225/55/18/102 V			
Winter tyres:	Fr.L.	Firestone: 55%	Fr.R.	Firestone: 55%
	Re.L.	Firestone: 50%	Re.R.	Firestone: 50%
Tyre profile depth FL				4.6
Tyre profile depth FR				4.7
Tyre profile depth RL				4.8
Tyre profile depth RR				4.9
Tyre size FL				225/55 R 18 102 V
Tyre size FR				225/55 R 18 102 V
Tyre size RL				225/55 R 18 102 V
Tyre size RR				225/55 R 18 102 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				258
Tyre make FR				258
Tyre make RL				258
Tyre make RR				258

Assistance equipment

Emergency spare wheel	Yes
Malfunction indicator, Blinking, Check	



Floor mat F, Tear, Replace



Seat cover FL, Tear, Replace



Outer backrest protection R, Scratch(es), Acceptable



Interior, Stain, Cleaning



Roof liner, Tear, Repair/replace (lump sum)



Dashboard, Scratch(es), Acceptable



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Tyre FL, Out of tolerance, Replace



Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Tyre RL, Out of tolerance, Replace



Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Tyre RR, Out of tolerance, Replace



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Tyre FR, Tear, Replace





Wing FL, Dent(s) and scratch(es), Repair and paint (complete)



Door FL, Dent(s) and scratch(es), Acceptable



Wing trim FL, Scratch(es), Replace




Bumper F, Scratch(es), Paint



Bumper moulding F, Scratch(es), Paint



Rear roof pillar covering R, Scratch(es), Repair/replace (lump sum)



Rear roof pillar covering L, Scratch(es), Repair/replace (lump sum)



Tailgate / Boot, Scratch(es), Acceptable



Reflector, Unclashed, Dismount/Mount



Historique Maintenance

Immatriculation: **GF-019-DR** Date de 1ère immatriculation: **11/03/2022**

Modèle: **Peugeot 5008 BlueHDi 130 S&S Allure Pack VP [5P] bvm 6-130CH-7cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
12/12/2025	83.390	EUROFLEET TYRES AND SERVICES	GARDIENNAGE
	0		PERMUTATIONS PNEUS
16/07/2025	74.457	SERVICE AUTOMOBILE DU CYGNE D'ENGHIEN	REVISION
19/05/2025	71.214	EUROFLEET TYRES AND SERVICES	PERMUTATIONS PNEUS
	0		GARDIENNAGE
20/01/2025	64.488	EUROFLEET TYRES AND SERVICES	GARDIENNAGE
	0		PERMUTATIONS PNEUS
24/07/2024	50.006	SERVICE AUTOMOBILE DU CYGNE D'ENGHIEN	REVISION ET CLIM
	0		BALAIS ESSUIE GLACE AV
	0		LIQUIDE DE FREIN
	0		PLAQUETTES AV RPLT
04/01/2024	35.000	EUROFLEET TYRES AND SERVICES	PERMUTATIONS PNEUS
	0		GARDIENNAGE
24/07/2023	23.866	SERVICE AUTOMOBILE DU CYGNE D'ENGHIEN	REVISION
16/02/2023	13.340	EUROFLEET TYRES AND SERVICES	GARDIENNAGE
	0		REMPLACEMENT PNEUS HIVER
30/01/2023	12.260	EUROFLEET TYRES AND SERVICES	REMPLACEMENT PNEUS ETE