


Vehicle details

VIN	YSM4ZPAAX TF430471	Registration date	10/10/2025	Exterior Color	Snow Matte
Brand	Polestar	Licence Plate	N/A	Odometer	2 033 km
Model	Polestar 4 PA / 200 kW (272 PS)	Condition of the car	Mit Schaden		
Pre-damage	Yes	Pre-damage amount excl. VAT	3282.18 €	Pre-damage Comments	3282,18€ body_damage , bonnet

Inspection Details




Removable element

Emergency compressor kit	✓
Refill emergency kit	✓
Toolkit	✓
Triangle	✓
Rear parcel shelf	✓
Floor mat BR	✓
Floor mat BL	✓
Floor mat FR	✓
Floor mat FL	✓

Technical Document

User manual	✓
Warranty booklet	✓
Log books	✓
First aid kit	✓
Inspektion	✓
Ladekabel Starkstrom-Steckdose	✓

Tyres



Exterior

1		Part	Door	Repair Time	0.60	Part Cost	-
		Position	Back left	Repair Cost	54.00€	Net Cost	54.00€
		Damages	Dented - Smart repair	Paint Time	-		
		Comments	-	Paint cost	-		
				Flat Rate	54.00€		
2		Part	Tailgate / Boot door	Repair Time	0.60	Part Cost	-
		Position	-	Repair Cost	54.00€	Net Cost	54.00€
		Damages	Dented - Smart repair	Paint Time	-		
		Comments	-	Paint cost	-		
				Flat Rate	54.00€		
3		Part	Door	Repair Time	0.60	Part Cost	-
		Position	Front right	Repair Cost	54.00€	Net Cost	54.00€
		Damages	Dented - Smart repair	Paint Time	-		
		Comments	-	Paint cost	-		
				Flat Rate	54.00€		
4		Part	Other bodywork	Repair Time	-	Part Cost	-
		Position	-	Repair Cost	-	Net Cost	-
		Damages	For info	Paint Time	-		
		Comments	-	Paint cost	-		
				Flat Rate	-		

Estimated repair cost

Total	162.00€
--------------	----------------