



BMW 3 Touring				
Vinnnumber:	WBA11FZ050FN31437	Versionname:		
First Registrationdate:	3/08/2022	Fiscalpower:		
Expertise Mileage:	141553	Power Kw:	100	
Bodytype:		Body colour	Black	
Gearbox:	Automatic	Type of rims (mounted)	Aluminium	
Transmission:		Parking lot	1730	
Fueltype:	Hybrid Diesel			
Type of rims (mounted)	Aluminium			
Certificate of Conformity	Yes			
Category	Passenger Car			
Registration Certificate Car (BE)	Yes			
Registration Certificate Home (BE)	No			
Options				
Number of keys total	2	Luggage cover		
Cruise Control		Front parking sensors		
Steering wheel multifunctional		Rear parking sensors		
Radio multimedia		Type of Tow bar	No Tow bar	
Type of headlighting	Headlighting LED			
Type of GPS	GPS big screen color			
Type of Lining	Lining artificial leather			
Type of climate control	Autom climate control			
Limited Technical Inspection				
Tyres				
Summer tyres:	225/50/17/98 V			
	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	BF Goodrich: 4 mm	Re.R.	BF Goodrich: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				225/50 R 17 98 V
Tyre size FR				225/50 R 17 98 V
Tyre size RL				225/50 R 17 98 V
Tyre size RR				225/50 R 17 98 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				255
Tyre make RL				2485
Tyre make RR				2485
Assistance equipment				
Number of charging cables (normal)	0			
Number of charging cables (rapid charge)	0			
Total cost ex VAT				1638,09
Interior, Damaged, Acceptable				0,00



Bumper F, Scratch(es), Repair and paint (complete)	296,58
--	--------



Windscreen, Stone chip(s), Acceptable	0,00
---------------------------------------	------



Alloy rim RL, Scratch(es), Acceptable	0,00
---------------------------------------	------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------



Rear window, Scratch(es), Replace	667,22
-----------------------------------	--------



Alloy rim FR, Scratch(es), Repair and paint (complete)	133,03
--	--------



Wing RR, Dent(s) and scratch(es), Acceptable	0,00
--	------



Door RR, Bad repair, Repair and paint (complete)	445,79
--	--------



Door FR, Dent(s), Paintless dent repair	95,47
---	-------



Door RR, Scratch(es), Acceptable	0,00
----------------------------------	------



Roof, Dent(s), Acceptable	0,00
---------------------------	------

