

MACADAM ITALY S.R.L. Piazza Belgioioso, 2 - 20121 Milano (MI) Tel. - Fax Piva: 12729790969				Report No.		Expert's report for Alphabet Italia				Type of insurance Perizia											
				Policyholder				Opposite party				Opposite party company									
				Operation 2026		Claim number			Code / Agency				Date accident 15/07/2026								
				Expert code			Adjuster code			Policy number				Injured person can recover the VAT							
Date assignment 15/07/2026		Date first survey 16/07/2026		Place Genova		C/O		Repairs		Photo		Lien in favor of		Expiry date							
Ownership certificate Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN)														Formerly plate							
Lessee / Co-owner														Date of overhaul							
Vehicle (Brand - Model - Version) CUPRA Formentor 2.0 TDI 4Drive DSG (110Kw) Suv 5p/d/1968								Plate GN205HH		Vin Chassis VSSZZZKM7PR045149				First Registration 21/03/2023							
Usage status NON CONOSCIUTO		Km 41136		Tyres % 50		Color Grigio		Type of enamel METALLIZED/DOUBLE				Consistency of damage		Type of Expert's report NOT DEFINITIVE							
Equipment																					
Approval code		For commercial vehicles		Carrying Qls 0		Tare, Q 0										Wheelbase		Seats No. 0		Axles 0	
Commercial value (C)		Wrecked car value		Value by difference		Ancillary expenses															
Damaged items / restoration operations								SR		LA		VE		ME		D.M. S.C.		Costs of spare parts			
								Dif		Time		Dif		Time		Time		* (VAT excluded)			
1	Codice Ricambio	2° chiave																			
1	Codice Ricambio	Pannello int. porta post. PRM						L													
1	Codice Ricambio	Ossatura vano porta post.						L	L		L		L								
1	Codice Ricambio	Ossatura vano porta post.						R	L		L		L								
1	Codice Ricambio	Ossatura vano porta post.						R	L		L		L								
1	5FF805904A9DG	Front bumper side spoiler						R	S		S		S								
1	5FF805903A9DG	Front bumper side spoiler						L	S		S		S								
1	5FF805902A041	Cover for lower front bumper							M		M		M								
1	Codice Ricambio	Rettifica cerchio in lega ant.						L													
1	5FF853717F9DG	Front wheel arch trim						L	L		L		L								
1	Codice Ricambio	Rivestimento int. lat. sedile post. PRM						R													
1	5FF854939BGRU	Trim of front door						L	S		S		S								
1	5FF831051	Front door						L	L		L		L								
1	5FF853817H9DG	Rear wheel arch trim						L	L		L		L								
1	Codice Ricambio	Rettifica cerchio in lega post.						L													
1	Codice Ricambio	Pneumatico post.						L	S		S		S								
1	5FF945307B	Rear internal part headlamp							S		S		S								
1	5FF807434G9DG	Rear bumper							M		M		M								
1	5FF807568B041	Rear bumper lower cladding							L		L		L								
1	Codice Ricambio	Cerchio in lega post. PRM						R													
1	Codice Ricambio	Modanatura arco passaruota post. PRM						R													
1	5FF854940BGRU	Trim of front door						R	S		S		S								
1	5FF854950BGRU	Trim of rear door						R	L		L		L								
1	5FF833052	Rear door						R	L		L		L								
1	5FF821022A	Front mudguard						R	L		L		L								
1	Codice Ricambio	Modanatura arco passaruota ant. PRM						R													
1	Codice Ricambio	Rettifica cerchio in lega ant.						R													

New for old value (N)	Remarks
	Pneumatici M S GOODYEAR 245/45 R18