



Ford Kuga: 2BPW464

Vinnumber:	WF0FXXWPMHNL37574	Versionname:	
First Registrationdate:	9/02/2022	Fiscalpower:	
Expertise Mileage:	122529	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front		
Fueltype:	Hybrid Petrol		
Maintenance:	OK		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Central consol F:	
Number keys remote:	2	Front parking sensors:	
Windows electric F:		Roof bar black:	
Windows electric R:		Type of Tow bar:	No Tow bar
Board Computer:			
Cruise Control:			
Steering wheel multifunctional:			
Steering wheel leather:			
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Autom climate control		
Type of GPS storage:	HD		

Tyres

225/60/18/104 V				
Winter tyres:	Fr.L.	Hankook: 4 mm	Fr.R.	Hankook: 4 mm
	Re.L.	Hankook: 6 mm	Re.R.	Hankook: 6 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				225/60 R 18 104 V
Tyre size FR				225/60 R 18 104 V
Tyre size RL				225/60 R 18 104 V
Tyre size RR				225/60 R 18 104 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				260
Tyre make FR				260
Tyre make RL				260
Tyre make RR				260

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	1		
Number of charging cables (rapid charge):	0		

Bumper F, Scratch(es), Acceptable



Alloy rim FL, Scratch(es), Acceptable



Charging cable (fast), Missing, Check



Boot lid covering R, Scratch(es), Smart repair



Internal boot lining R, Scratch(es), Acceptable



Bumper R, Scratch(es), Spot repair



Alloy rim FR, Scratch(es), Repair and paint (complete)

