



IDENTIFICATION VEHICLE

Driver name:	ASSE I
Make:	BMW
Model / version:	1 SERIES HATCH
Vin:	WBA7M710905U98404
Mileage:	87374
First registration:	11/02/2022
Color:	SAPHIRSCHWAR




ADDITIONAL INFORMATION


Category:
Transmission:
Interior color:
Metallic paint: ?
Type of lining:
Board computer reset: ?

DOCUMENTS

Certificate of conformity: ✓
Registration certificate: ✓
Registration certificate 2: ✓
Insurance certificate: ?
Maintenance book:
Number of keys: 2
Original key: ✓

PICTURES





VIN INFORMATION

Transmission séquentielle

Matière : alliage

Diamètre arrière 16

Diamètre avant 16

Hauteur arrière 55

Largeur avant 205

Diesel

85 kw

Rétroviseur intérieur jour/nuit automatique

Garnitures tissu

Caméra avant

Attelage avec boule amovible

Assistant maintien de la voie

Avertisseur de collision avant

Avantage

pack de rangement

spécifique Europe

7 rapports

Lettre repère (J)

Largeur avant 7,0

Diamètre arrière 16

Indice de vitesse avant W

Largeur arrière 205

1496 cm3

116 ch

Siège avant gauche réglable en hauteur

Aide au stationnement avant

Régulateur automatique de la distance

Airbag passager désactivable

Freinage d'urgence assistée autonome (urbain)

Contrôle pression des pneus

mesures CO2 étendues

BMW Live Cockpit Plus

Projecteurs à LED

Diamètre avant 16

Largeur arrière 7,0

Hauteur avant 55

Indice de vitesse arrière W

Climatisation réfrigérant 1234YF

1.50 litre

Métallisée vernissée

Sièges avant réglable en hauteur

Aide au stationnement arrière

Appel de secours

Protection piéton

Avertisseur d'angle mort

depuis 01.22

tuner DAB

encarts intérieurs argent Quartz mat

nervuré

EQUIPMENT

Board computer:



Compressor:



Central locking:



Cruise control:



Gps:	?	Power steering:	?
Rear parking sensor:	?	Repair kit:	×
Front seats heated:	?	Steering wheel:	?
Electric windows:	?	Climate control type:	
Headlighting type:		Tow bar type:	
Charging cables:	0	Fast charging cables:	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	3 mm			Summer		?
Front right	3 mm			Summer		?
Rear left	3 mm			Summer		?
Rear right	3 mm			Summer		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Tyre repair kit	Missing
2	Bumper F	Dent(s) and scratch(es)
3	Wing FL	Dent(s) and scratch(es)
4	Door FL	Scratch(es)
5	Door RL	Dent(s)
7	Alloy rim FL	Dent(s) and scratch(es)

Total: 6

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
6	Bodywork	Dent(s) and scratch(es)	✓	×	×

Total: 1

DAMAGES DETAILS

1 - Tyre repair kit - Missing



2 - Bumper F - Dent(s) and scratch(es)



3 - Wing FL - Dent(s) and scratch(es)





4 - Door FL - Scratch(es)




5 - Door RL - Dent(s)



7 - Alloy rim FL - Dent(s) and scratch(es)



6 - Bodywork - Dent(s) and scratch(es) - Renta®



SIGNATURE

Expert