MACADAM










Ford Focus: N972FH

Vinnumber:	**WF0PXXGCHPMC70423**	Versionname:	**Focus 1.5 EcoBoost 110kW ST-Line X Business wagon automaat**
First Registrationdate:	**29/09/2021**	Fiscalpower:	
Expertise Mileage:	**183360**	Power Kw:	**110**
Bodytype:		Body colour	**Agate Black**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Petrol**	Parking lot	**838**
Number of seats	**5**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**No**		

Options

Number of keys total	**2**	Rear parking sensors	
GPS		Hook	
Autom climate control		Rear view camera	
Radio multimedia			

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 50 / 17 / 95 / W / Aluminium	5,1 mm	Bridgestone	Summer
	Right	215 / 50 / 17 / 95 / W / Aluminium	4,7 mm	Bridgestone	Summer
Rear	Left	215 / 50 / 17 / 95 / W / Aluminium	5,1 mm	Bridgestone	Summer
	Right	215 / 50 / 17 / 95 / W / Aluminium	3,6 mm	Bridgestone	Summer

Assistance equipment

Interior, Stain, Cleaning






Door FL, Scratch(es), Repair and paint (complete)







Door RL, Scratch(es), Repair and paint (complete)



Wing FL, Scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Repair and paint (complete)



Bonnet, Scratch(es), Polish



Windscreen, Stone chip(s), Windscreen repair



Bumper F, Stone chip(s), Repair and paint (complete)



Door RR, Scratch(es), Polish



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)







Wing RR, Scratch(es), Repair and paint (complete)










Roof pillar R, Scratch(es), Polish






Bumper R, Scratch(es), Repair and paint (complete)











Tailgate / Boot, Scratch(es), Polish







Rear window, Scratch(es), Replace








Roof, Scratch(es), Polish






Onderhoudshistorie van: WF0PXXGCHPMC70423

ALPHABET

Kenteken	N972FH
Merk Model	Ford Focus 1.5 EcoBoost 110kW ST-Line X Business wagon automaat
Brandstofsoort	Benzine
Datum deel1	9/29/21

Datum reparatie	Kilometerstand	Reparatie omschrijving
4/21/26	167,568	Onderhoudsbeurt
10/31/25	148,328	Vervanging band
9/11/25	141,365	APK
9/11/25	141,365	Onderhoudsbeurt
9/11/25	141,365	Vervanging band
7/7/25	133,144	Remblokken achterzijde
7/7/25	133,144	Remblokken voorzijde
6/2/25	127,944	Reparatie band(en)
4/17/25	120,134	Vervanging band
9/9/24	114,575	Onderhoudsbeurt
6/16/23	90,834	Onderhoudsbeurt
6/16/23	90,834	Remblokken voorzijde
6/16/23	90,834	Sleutelbatterij
3/7/23	77,415	Reparatie band(en)
11/9/22	60,771	Onderhoudsbeurt
7/18/22	45,601	Reparatie band(en)
4/25/22	31,502	Onderhoudsbeurt