

# MACADAM



**SKODA SUPERB COMBI:**

Vinnumber:	<b>TMBJW7NP2M7031667</b>	Versionname:	<b>1.4 TSI iV 160kW DSG6 Ambition</b>
First Registrationdate:	<b>20/11/2020</b>	Fiscalpower:	
Expertise Mileage:	<b>111840</b>	Power Kw:	<b>160</b>
Bodytype:		Body colour:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>3425</b>
Fueltype:	<b>Hybrid Petrol</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Number of keys total	<b>2</b>	Seats electric F L	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	<b>Tow bar collapsible</b>
Type of headlighting	<b>Headlighting LED</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

**Tyres**

<b>215/55/17/92 H</b>				
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>
Tyre profile depth FL				<b>5.0</b>
Tyre profile depth FR				<b>5.0</b>
Tyre profile depth RL				<b>5.0</b>
Tyre profile depth RR				<b>5.0</b>
Tyre size FL				<b>215/55 R 17 92 H</b>
Tyre size FR				<b>215/55 R 17 92 H</b>
Tyre size RL				<b>215/55 R 17 92 H</b>
Tyre size RR				<b>215/55 R 17 92 H</b>
Tyre type FL				<b>Summer</b>
Tyre type FR				<b>Summer</b>
Tyre type RL				<b>Summer</b>
Tyre type RR				<b>Summer</b>
Tyre make FL				<b>261</b>
Tyre make FR				<b>261</b>
Tyre make RL				<b>261</b>
Tyre make RR				<b>261</b>

**Assistance equipment**

Number of charging cables (normal)	<b>1</b>
Number of charging cables (rapid charge)	<b>1</b>

Total cost ex VAT	<b>1569,37</b>
Bonnet, Chemical polution, Repair and paint (complete)	<b>487,44</b>



Grille, Crack, Replace 546,98



Windscreen, Stone chip(s), Windscreen repair 0,00



Bumper R, Scratch(es), Acceptable 0,00



Door FR, Scratch(es), Acceptable 0,00



Door RR, Chemical pollution, Repair and paint (complete) 534,95



Roof, Chemical pollution, Polish 0,00

