DEKRA

DEKRA Automotive Solutions

Appraisal Report

Vehicle details

VIN	ZARPAHPX9 R7D96004	Registration date	30/01/2025	Exterior Color	Unknown
Brand	ALFA ROMEO	Licence Plate	EU-FA 9474	Odometer	44 990 km
Model	STELVIO 2.2 Diesel 16V 154kW Veloce AT8-				

Inspection Details

Arrival Date	17/08/2026	Inspection ID	7124399	Inspection date	24/08/2026
Assign Date	17/08/2026	Fleet owner	Leasys FINN	Inspection loc.	Leasys AKB Schöneck




















Generic equipment

Removable element

Spare wheel kit	✓
Load cover	✓
Floor mat BR	✓
Floor mat BL	✓
Floor mat FR	✓
Floor mat FL	✓


Technical Document

User manual	✓
Warranty booklet	✓
Log books	✓
Spare key	✓
Key	✓
Remote key	✓
Service	✗

Tyres

Pirelli 255/45/20 Y All seasons 4.0 mm

Pirelli 255/45/20 Y All seasons 4.0 mm






Pirelli 255/45/20 Y All seasons 5.0 mm

Pirelli 255/45/20 Y All seasons 5.0 mm

Exception / Damage

1



Part	Service	Repair Time	-	Part Cost	300.00€
Position	-	Repair Cost	-	Gross Cost	300.00€
Damages	Missing	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Replace	Flat Rate	-	**Net Cost**	**300.00€**

DEKRA

DEKRA Automotive Solutions

Appraisal Report

2



Part	Door	Repair Time	-	Part Cost	-
Position	Front left	Repair Cost	-	Gross Cost	50.00€
Damages	Scratched	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Polishing	Flat Rate	50.00€	**Net Cost**	**50.00€**

Summary Inspection

Gross Price	350.00€	Depreciation	-	Net Price	350.00€

Labor cost summary

	Hourly Rate	Time	Gross Price	Depreciation %	Depreciation	Net Price
Bodywork	0.00€	0.00	0.00€	-	-	0.00€
Paintwork	0.00€	0.00	0.00€	-	-	0.00€
Paint preparation	0.00€	0.00	0.00€	-	-	0.00€

Miscellaneous

	Gross Price	Depreciation %	Depreciation	Net Price
Small parts / disposal charge	0.00€	-	-	0.00€
Part Cost	300.00€	-	-	300.00€
Flat Rate	-250.00€	-	-	-250.00€