



Expertise

Protocol number: 46443577
Order No. / Reference: 26617362
Inspection date: 9 Jul 2026

Manufacturer: Mercedes-Benz

Model: Vito 114 CDI Kompakt HA Aut. BASE

VIN: W1V44760114118991



Vehicle details

Manufacturer / Type / Model / Equipment

Mercedes-Benz Vito 114 CDI Kompakt HA Aut. BASE

Vehicle Identification number W1V44760114118991
Mileage (Read) 77,818 km
First registration 9 Jun 2022
Number of holders 1

Power / Engine displacement 100 kw / 1,950 ccm
Fuel type / Cylinder Diesel / 4
Gearbox / Number of gears Automatic / 9
Type of drive Rear drive
Type of vehicle Van

Colour / colour code VERKEHRSBLAU
Doors / Seats 4 / 3
Upholstery type Cloth
Colour of upholstery Grey-Black



Vehicle details			
Maintenance booklet / proof	digital proof / complete	Next maintenance in	487 Tag(e)
Last service on / at	11/2025 at 61,716 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GM177599
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	2222 / BBT 04150		
Emission standard	EUROVI; D; M, N	fine dust sticker	
Permitted total weight	2,800 kg	Empty weight	

Tyres				
Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/65 R16 103H	All-season tyres on Steel rim with wheel cover	Continental	6mm / 6mm
2)	205/65 R16 103H	All-season tyres on Steel rim with wheel cover	Continental	5mm / 5mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- | | |
|---|--|
| <ul style="list-style-type: none"> • Screw-in towing eye front/rear • Driver's side airbag • Exterior mirrors, manually adjustable (2) • Battery: Backup battery for starting process • Fixing points in the roof frame • third brake light • COC documents • Diesel particulate filter • Electronic Stability Program (ADAPTIVE ESP) with integrated Anti-lock Braking System (ABS) • Electric windows, driver/passenger • Generator 14 V / 200 A • Speed limit 210 km/h • Weight variant 2,800 kg • Seatbelt warning device for driver's seat • Main tank 57 liters • Interior trim of cargo area, side • Communication module (LTE) for digital services • Paint finish: Solid color paint • Headlight range control • Multifunctional steering wheel • Breakdown management • Tires: 195/65 R 16 • Tires: Premium protection tires (3 years) • Wheels: Steel rims 6.5 J x 16 • Sliding door on the right, cargo/passenger compartment • Crosswind Assist • Seats: Adjustable passenger seat • Start-stop function • Cruise control • First aid kit • Warning triangle • Immobiliser • Central locking with radio remote control • Registration certificate, Part II | <ul style="list-style-type: none"> • Passenger side airbag • ATTENTION ASSIST • Outdoor temperature display • Battery: fleece battery 12 V / 92 Ah • Hill start assist • Brake lights, adaptive • Front cupholder • Electronic tachometer • Chassis: Standard chassis • HVO-capable vehicle • Parking brake • Generator management • Transmission: 9G-TRONIC • Seatbelt warning device for front passenger seat • Lockable glove box • Boot lid • Instrument cluster with pixel matrix display • Headrests (2), front • Steering wheel adjustable for tilt and height • Mercedes-Benz emergency call system • Package: BlueEFFICIENCY • Upholstery: Caluma fabric, black • Tires: Tires without specified make • Tires: Summer tires • Headlights: halogen technology • Key: 3-button remote control • electromechanical power steering • Seats: Driver's seat • 12V socket • continuous partition wall • Pre-installation for Remote Services Plus • Maintenance interval indicator >>ASSYST< • Heat-insulating glass all around • Registration as a truck |
|---|--|

Extra equipment

- | | |
|--|---|
| <ul style="list-style-type: none"> • Trailer hitch • Driving light assistant • Generator 14 V / 250 A • Wooden floor (cargo area) • Tempmatic controlled air conditioning • Navigation accessories: Live Traffic Information • Rain sensor • Tires: All-season tires • Seats: Passenger seat, two-seater • Partition wall with 1 continuous window | <ul style="list-style-type: none"> • Comfort roof control unit in conjunction with rain sensor • Window in tailgate • Rear camera not foldable • Interior lining of the cargo area up to roof height • Large fuel tank, approx. 70 liters • Radio: Digital Radio DAB • Tires: 205/65 R 16 • High-resolution reversing camera with guide lines • Seats: Comfort driver's seat • Auxiliary heater, electric |
|--|---|



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Door - front left side	Door - dent(s) - Smart repair
3	Side panel - rear left side	Side panel - Scratch(es) - Smart repair

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Comments

Die Unterbodenbesichtigung war nur ebenerdig und eingeschränkt möglich. Mehrkosten möglich



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents



Figure 15: Navigation



Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.




Damage 2: Door - front left side: Door - dent(s) - Smart repair



Damage 2: Door - front left side: Door - dent(s) - Smart repair



Damage 3: Side panel - rear left side: Side panel - Scratch(es) - Smart repair



Damage 3: Side panel - rear left side: Side panel - Scratch(es) - Smart repair



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W1V44760114118991

Hersteller / Modell: MERCEDES-BENZ MERCEDES-BENZ Vito 114 CDI Kompakt HA
Aut. BASE

Datum	KM-Stand	Beschreibung
06.11.2025	61.716	Regelwartungsdienst
25.07.2024	49.021	AU
21.11.2023	31.253	Bremsinspektion vo + hi; Regelwartungsdienst