


Vehicle details

VIN	LRWYGCEKX NC351057	Brand	TESLA	Maintenance date	-
Licence Plate		Model	Model Y Long Range Dual Motor AWD	Maintenance mileage	-
Registration date	29/06/2022	Year	2022	Exterior Color	Red Metallic
Odometer	144 792 km	Engine size	-	Interior Color	Black
Fuel	Electric	Body Type	Minivan	Next technical inspection	-
Seats	5	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	10/07/2026	Inspection loc.	
-----------------	------------	-----------------	--



Generic equipment	Removable element	Technical Document
Automated air-conditioning ✓	Rear parcel shelf ✓	Spare key ✓
Cruise control ✓	Vehicle charger ✓	Card Key ✓
Leather ✓	Wireless charger ✓	Sat Nav CD ROM Software ✓
GPS system ✓		
Panoramic roof ✓		
Alloy wheel rims ✓		
Automatic Gearbox ✓		
Heating seats ✓		
Electric seats ✓		
Tow ✓		
Metallic paint ✓		
Central locking ✓		
Electric windows ✓		
4x4 ✓		
Park Distance Control ✓		
Audio System ✓		
Led lighting ✓		

Tyres

Michelin 255/40/20 Summer 4.0 mm			Michelin 255/40/20 Summer 4.0 mm	
Michelin 255/40/20 Summer 5.0 mm			Michelin 255/40/20 Summer 5.0 mm	

Exterior

1		Part Alloy wheel 20" Position Front left Damages Scratched Severity - Repair mode Lumpsum repair	2		Part Rocker panel cap Position Back left Damages Scratched Severity - Repair mode Smart Repair
3		Part Alloy wheel 20" Position Back left Damages Scratched Severity - Repair mode Lumpsum repair	5		Part Wing Position Back right Damages Scratched Severity - Repair mode Repair
6		Part Alloy wheel 20" Position Back right Damages Scratched Severity - Repair mode Lumpsum repair	7		Part Rocker panel cap Position Back right Damages Scratched Severity - Repair mode Smart Repair
8		Part Door Position Back right Damages Dent & Chips Severity - Repair mode Repair	9		Part Alloy wheel 20" Position Front right Damages Scratched Severity - Repair mode Lumpsum repair

10



Part	Bumper
Position	Front
Damages	Broken
Severity	-
Repair mode	Replace

12



Part	Bonnet
Position	-
Damages	Dent & Chips
Severity	-
Repair mode	Repair

Interior damage

4




Part	Boot carpet
Position	-
Damages	Scratched
Severity	-
Repair mode	For info



Others

11



Part	Damage appraisal
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info