

## Volkswagen Caddy 2.0 TDI L1H1 BMT Trendline (Bestel)

Contact Summary

License plate	VS-752-T	Fuel	Diesel
VIN	WV1ZZZ2KZGX077052	Transmission	Manual
Brand	Volkswagen	Doors	4
Model	Caddy	Seats	2
Model Type	2.0 TDI L1H1 BMT Trendline (Best...	Color	Unknown
VAT/Margin	VAT	Interior Color	Black
Mileage	176803 Km	Interior Type	Fabric
Expected mileage	176803 Km	Paint type	
Available per	Direct	NAP status	Logical

### Vehicle Details

#### History

Manufacture year	2016
First registration	26-01-2016 (NL)
Current registration	26-01-2016 (NL)
Imported	No

Model year	15-04-2015 → 31-12-2020
Used as	Normal
Immigration good	No
Vehicle Source	Dealer

#### Environment

Energy label	
CO2 emission (NEDC)	117
EU category	Euro 6

#### Engine & performance

Power	55 kw
Cylinders	4
Engine	1968
Drivetrain	Frontwheeldri...

#### Financial

BPM deductible	No
Gross BPM	€ 5892
Rest BPM	€ 997

#### Weights

Empty weight	2127
Towing weight	0
Wheel base	268

#### Remark

Parking Location	L17
------------------	-----

### Features

#### Specific features

Hill hold function  
Front head airbag(s).  
Multimedia preparation  
Passenger airbag  
Passenger seat height adjustable  
Radio  
Start/stop system  
Front side airbag(s).  
**Sliding side door on the right**











Driver's seat adjustable in height  
Bluetooth  
On-board computer  
Brake Assist System  
Exterior mirrors electrically adjustable and hea...  
Central locking with remote control  
Electric windows in front  
Electronic limited slip differential  
Electronic Stability Program

**Cruise control**  
Rear doors with windows  
Rear window heating  
Rear window wiper  
**Air conditioning**  
Alarm class 1 (immobilizer)  
Anti blocking system  
Anti-slip Regulation  
Driver's airbag

#### Packages

### Conditions

#### Optical issues

Scratch(es)	
Front bumper	
Scratch(es)	
Rear bumper	
Dent(s)	
Rear left screen	
createpage.OpticalDamages.Description.Cl...	
Rear right door	
createpage.OpticalDamages.Description.Cl...	
Tailgate/coverge	
Restyle dent(s)	
Roof	
Breakage	
Windshield	
Burn hole	
createpage.OpticalDamages.Part.frontseat...	
Stains	
createpage.OpticalDamages.Part.frontseat...	
Wear and tear	
Steering wheel	

### Technical inspection & maintenance

Technical inspection	08-05-2027
Maintenance history	Ok
Last date of maintenance	07-05-2025
Odorless	Yes

Keys	2
Driveable	Yes

### Tyres

AllSeason	Average
-----------	---------

### Owner history

Date	Extra info	Owner	Number Of Days
26-01-2016	Eerste toelating Datum deel IA / I	Lease	1829
28-01-2021		Lease	12
09-02-2021		Autobedrijf	70
20-04-2021		Overig zakelijk	1864
28-05-2026	Laatste tenaamstelling	Autobedrijf	22
08-05-2027	APK vervaldatum		-

### Summary



#### Volkswagen Caddy 2.0 TDI L1H1 BMT Trendline (Bestel)

Licence plate	VS-752-T	Technical damage	No
Mileage	176803 Km	Optical damage	Yes
Expected Mileage	176803 Km	Nr of Owners	3
Available per	19-06-2026	Used as	Normal
Transmission	Manual	BPM Reclaimable	No
Drivetrain	Frontwheeldrive	Catalog	Continuous
Power	55	Lot ID	13a1ff47-40f5-4...
VAT/Margin	VAT	Date	19-06-2026
NAP status	Logical	Remark	No
Manufacture year	2016		
Imported	No		
Country of origin	NL		