Volkswagen

VIN: WVWZZZAWZMU091262

Estimated repair cost

0.00 EUR
TOTAL



Description

Registration number 2EJC904	**First registration date** -	**Odometer** 53395 km
Color -	**Model year** -	**Upholstery** -
Number of doors -	**Number of seats** -	**Generation** -

Statement details

Inspection loc
PARC LIZY

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Loose Items

- ☑ Registration certificate
- ☑ Registration certificate owner
- ☑ Compressor tyre repair kit
- ☑ Spare Key
- ☑ Rear parcel shelf
- ☑ Document holder
- ☑ Refill tyre repair kit

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Main set of tyres

Front Left	KLEBER	195/55/16 96 V All-season	4 mm
Front Right	KLEBER	195/55/16 96 V All-season	4 mm
Back Left	KLEBER	195/55/16 96 V All-season	4 mm
Back Right	KLEBER	195/55/16 96 V All-season	4 mm

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures


Front left


Rear left



Boot opened


Rear right


Rear passenger compartment


Dashboard from rear seat


Front passenger compartment


Front right



Odometer



Navigation


Spare Tyre



Vin

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Other

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.