


Vehicle details

VIN	5YJ3E7EA0 KF526299	Brand	TESLA	Maintenance date	-
		Model	Model 3 Standard Plus RWD	Maintenance mileage	-
Registration date	06/11/2019	Year	2019	Exterior Color	Midnight Silver
Odometer	253 468 km	Engine size	-	Interior Color	Unknown
Fuel	Electric	Body Type	Saloon / Hatchback	Next technical inspection	-
Seats	5	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date 09/07/2026



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Leather	✓
GPS system	✓
Panoramic roof	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element


Rear parcel shelf	✓
Vehicle charger	✓
Wireless charger	✓

Technical Document

Spare key	✓
Card Key	✓
Sat Nav CD ROM Software	✓

Tyres

Pirelli 235/45/18 Summer 5.0 mm



Pirelli 235/45/18 Summer 5.0 mm



Pirelli 235/45/18 Summer 5.0 mm

Pirelli 235/45/18 Summer 5.0 mm

Exterior

1



Part	Step plate
Position	Back left
Damages	Scratched
Severity	-
Repair mode	For info

3



Part	Wing
Position	Front left
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

4



Part	Alloy wheel 18"
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

5



Part	Wing
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Repair

6



Part	Alloy wheel 18"
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

7



Part	Bumper
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Repair

8



Part	Wing
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Repair

9



Part	Alloy wheel 18"
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

10



Part	Sill
Position	Right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

11



Part	Door
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Repair

12



Part	Door
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Repair

13



Part	Alloy wheel 18"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

14



Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Repair

Interior damage

2



Part	Interior tailgate lining
Position	-
Damages	Scratched
Severity	-
Repair mode	For info