



RENAULT KANGOO FURGÓN L1 1.5 Blue dCi 70kW (95CV) furgón derivado de turismo 70KW (95CV) 4P manual: 5723-MCS

Vinnumber:	VF1RFK00170152217	Versionname:	
First Registrationdate:	5/12/2022	Fiscalpower:	0
Expertise Mileage:	42866	Power Kw:	
Bodytype:	Transporter	Body colour:	White
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Steel
Transmission:			
Fueltype:	Diesel		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	2		
Number head rests:	2		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Light Commercial Vehicle		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Radio:	
Number keys remote:	2	Rear parking sensors:	
Windows electric F:			
Cruise Control:			
Steering wheel multifunctional:			
Type of climate control:	Manual climate control		

Tyres

	195/65/15/95 H			
Summer tyres:	Fr.L.	Goodyear: 2 mm	Fr.R.	Goodyear: 2 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL				2.0
Tyre profile depth FR				2.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				195/65 R 15 95 H
Tyre size FR				195/65 R 15 95 H
Tyre size RL				195/65 R 15 95 H
Tyre size RR				195/65 R 15 95 H
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit:	Yes
-------------	------------

Interior, Dirty, Cleaning



Malfunction indicator, Blinking, Check



Interior, Damaged, Check



Steel rim RL, Scratch(es), Repair/replace (lump sum)



Bumper F, Scratch(es), Acceptable



Bonnet, Dent(s) and scratch(es), Repair and paint (complete)



Steel rim RR, Scratch(es), Repair/replace (lump sum)



Rear panel, Dent(s) and scratch(es), Repair and paint (complete)



Internal boot lining L, Scratch(es), Acceptable



Internal boot lining L, Scratch(es), Acceptable



Internal boot lining R, Scratch(es), Acceptable



Internal boot lining R, Scratch(es), Acceptable



Boot door panel RL, Scratch(es), Acceptable




Boot carpet, Tear, Replace



Bumper R, Scratch(es), Paint



Tyres, No damage, Check



Bodywork, Glue residues, Acceptable

