



Renault Clio: T875XH

Vinnumber:	VF1RJA00271590117	Versionname:	Clio 1.0 TCe 67kW GPF Equilibre
First Registrationdate:	29/09/2023	Fiscalpower:	
Expertise Mileage:	73296	Power Kw:	67
Bodytype:		Body colour	Speciale metaallak Bleu Iron
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:		Type of rims (mounted)	Steel
Fueltype:	Petrol	Parking lot	597
Number of seats	5		
Type of rims (mounted)	Steel		
Maintenance needed	No		

Options

Number of keys total	2
GPS	
Manual climate control	
Radio multimedia	

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	185 / 65 / 15 / 92 / T / Steel	4,8 mm	Goodyear	Winter
	Right	185 / 65 / 15 / 92 / T / Steel	5,0 mm	Goodyear	Winter
Rear	Left	185 / 65 / 15 / 92 / T / Steel	7,2 mm	Goodyear	Winter
	Right	185 / 65 / 15 / 92 / T / Steel	5,8 mm	Goodyear	Winter

Assistance equipment

Number of charging cables (rapid charge)	0
--	----------

Interior, Stain, Cleaning



Door FL, Scratch(es), Repair and paint (complete)



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)





Roof pillar L, Scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Polish



Door FR, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Replace and paint



Steel rim FR, Deformed / Strained, Replace



Roof pillar R, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)





Tailgate / Boot, Dent(s), Paintless dent repair



Kenteken	T875XH
Merk Model	Renault Clio 1.0 TCe 67kW GPF Equilibre
Brandstofsoort	Benzine
Datum deel1	29-09-23

Datum reparatie	Kilometerstand	Reparatie omschrijving
09-01-26	58.092	Bougie
09-01-26	58.092	Luchtfilter
09-01-26	58.092	Onderhoudsbeurt
09-01-26	58.092	Ruitenwissermotor
21-10-24	32.095	Onderhoudsbeurt
05-10-23	20	Vervanging band