

2-ETD-031

2-ETD-031 · 318iA Berline Business Edition · 6 August 2026 · Zaventem (BE)

Specifications

License Plate Number	2-ETD-031	Fuel Type	Gasoline
Manufacturer	BMW	VIN	WBA28FF0508E19541
Model	3-serie	Cylinder Capacity	1.998 ^{cm3}
Model Versions	318iA Berline Business Edition	Transmission Type	Automatisch geschakelde Transmissie
Body Type	Sedan / Limousine	First Admission	19-01-2024
Color	Black	Odometer	83.670 ^{Km}
Paint Type	Metallic	Numer Of Keys	2
Production Year	2024	Interior	Grey
KW	115	Number Headrests	5

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Steering wheel multifunction

Steeringwheel - Heated

Condition

Condition exterior

Adequate

Maintenance Remarks

Olie verversen over 19000 km

Condition interior

Adequate

Previous Repairs

Unknown

Last Maintenance Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	6 ^{mm}	Michelin	225 ^{mm}	50 ^{mm}	17 ^{inch}	Summer
Rear Left	6 ^{mm}	Michelin	225 ^{mm}	50 ^{mm}	17 ^{inch}	Summer
Front Right	6 ^{mm}	Michelin	225 ^{mm}	50 ^{mm}	17 ^{inch}	Summer
Rear Right	6 ^{mm}	Michelin	225 ^{mm}	50 ^{mm}	17 ^{inch}	Summer
Spare Tire Type	None					

Damages



Damage Part

Interior



Damage Type

Stains & dirt

Repair Type

Cleaning

Acceptable

No



Damage Part

Frontdoor – Right



Damage Type

Door-edge chipped

Repair Type

Acceptable

Acceptable

Yes



Damage Part

Fender – Rear Right



Damage Type

small dents / small scratches



Repair Type

Panelbeating & Spray

Acceptable

No



Damage Part

Reardoor – Right

Damage Type

Scratch(es)

Repair Type

Spray

Acceptable

No



Damage Part

Alloy – Right Front

Damage Type

Damaged

Repair Type

Rim repair

Acceptable

No



Damage Part

Bumper – Front

Damage Type

Small scratch(es)

Repair Type

Spotrepair

Acceptable

No