



Peugeot 308 (UKL): 2CEV050

Vinnumber:	VR3FBYH2LNY560296	Versionname:	308 Active Pack 1.5 BlueHDi S&S 130pk/cv 5p
First Registrationdate:	28/06/2022	Fiscalpower:	
Expertise Mileage:	104428	Power Kw:	96
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:	Diesel		
Maintenance	OK		
Maintenance	25200.0		
Maintenance	9 maand		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	205/55/16/94 V			
Summer tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				205/55 R 16 94 V
Tyre size FR				205/55 R 16 94 V
Tyre size RL				205/55 R 16 94 V
Tyre size RR				205/55 R 16 94 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				255
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit	Yes	Compressor	Yes
MOT certificate, Missing, Replace			



Interior, Dirty, Forfeit



Floor covering FL, Worn, Check



Floor covering FL, Burned, Smart repair



Roof liner, Burned, Smart repair



Door panel RL, Hole, Smart repair



Centre console, Scratch(es), Acceptable



Door panel RR, Scratch(es), Smart repair



Interior covering A pillar R, Scratch(es), Acceptable



Interior, Damaged, Acceptable



Bumper F, Scratch(es), Acceptable



Alloy rim FL, Scratch(es), Repair and paint (complete)



Wing FL, Dent(s) and scratch(es), Repair and paint (complete)



Mirror side repeater L, Broken, Replace



Door FL, Scratch(es), Repair and paint (complete)



Outer door handle FL, Scratch(es), Acceptable



Outer sill L, Scratch(es), Acceptable



Step L, Scratch(es), Acceptable




Roof pillar L, Scratch(es), Acceptable



Door RL, Scratch(es), Repair and paint (complete)



Alloy rim RL, Scratch(es), Repair and paint (complete)



Wing RL, Dent(s) and scratch(es), Acceptable



Rear bulkhead lining, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Tailgate / Boot, Scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable



Bumper trim R, Scratch(es), Acceptable



Wheel aperture RL, Dent(s) and scratch(es), Acceptable



Alloy rim FR, Scratch(es), Acceptable



Wing FR, Repaired, Check



Door FR, Repaired, Check



Roof pillar R, Scratch(es), Acceptable



Door RR, Repaired, Check



Wing RR, Repaired, Check



Wing RR, Scratch(es), Acceptable



Bodywork, Scratch(es), Acceptable



Kenteken	2CEV050
Merk Model	Peugeot 308 Active Pack 1.5 BlueHDi S&S 130pk/cv 5p
Brandstofsoort	Diesel
Datum deel1	6/28/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
12/5/25	90,357	90000 km	Uitvoeren
12/5/25	90,357	luchtfilter interieur	Vervangen
12/5/25	90,357	oliezeef	Vervangen
11/15/24	63,304	60000 km	Uitvoeren
11/15/24	63,304	brandstof hoofdfilter	Vervangen
11/15/24	63,304	luchtfilter	Vervangen
11/15/24	63,304	luchtfilter interieur	Vervangen
11/15/24	63,304	oliezeef	Vervangen
11/15/24	63,304	remvloeistof	Vervangen
11/24/23	32,149	30000 km	Uitvoeren
11/24/23	32,149	luchtfilter interieur	Vervangen
11/24/23	32,149	oliezeef	Vervangen