
MACADAM











BMW 1 Reeks (UKL): 2DHW997

Vinnumber:	**WBA7M710307M40907**	Versionname:	**116d (F40) 1.5d 116pk/cv 5p**
First Registrationdate:	**24/03/2023**	Fiscalpower:	
Expertise Mileage:	**38769**	Power Kw:	**85**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**MAN 6 VIT**		
Transmission:			
Fueltype:	**Diesel**		
Maintenance	**OK**		
Maintenance	**+ 3700 km**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Winter tyres:	**205/55/16/94 V**			
	Fr.L.	**Dunlop: 8 mm**	Fr.R.	**Dunlop: 8 mm**
	Re.L.	**Dunlop: 10 mm**	Re.R.	**Dunlop: 10 mm**

Tyre profile depth FL	**8.0**
Tyre profile depth FR	**8.0**
Tyre profile depth RL	**10.0**
Tyre profile depth RR	**10.0**
Tyre size FL	**205/55 R 16 94 V**
Tyre size FR	**205/55 R 16 94 V**
Tyre size RL	**205/55 R 16 94 V**
Tyre size RR	**205/55 R 16 94 V**
Tyre type FL	**Winter**
Tyre type FR	**Winter**
Tyre type RL	**Winter**
Tyre type RR	**Winter**
Tyre make FL	**257**
Tyre make FR	**257**
Tyre make RL	**257**
Tyre make RR	**257**

Assistance equipment

Seat cover FR, Stain, Cleaning







Outside rear-view mirror base L, Scratch(es), Smart repair




Outside rear-view mirror housing R, Scratch(es), Acceptable




Bodywork, Paint measurement, Acceptable



Onderhoudshistorie van: WBA7M710307M40907

ALPHABET

Kenteken	2DHW997
Merk Model	BMW 116d (F40) 1.5d 116pk/cv 5p
Brandstofsoort	Diesel
Datum deel1	3/24/23

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
5/27/26	31,288	BMW/MINI service standaard omvang	Uitvoeren
5/27/26	31,288	klein materiaal	
5/27/26	31,288	koelwatervloeistof	Bijvullen/-laden
5/27/26	31,288	remvloeistof	Vervangen
5/27/26	31,288	ruitenwisserrubber achter	Vervangen
5/27/26	31,288	ruitenwisserrubber vooraan	Vervangen
5/27/26	31,288	ruitenwisservloeistof	Bijvullen/-laden
4/15/25	18,657	batterij	Vervangen
4/15/25	18,657	BMW/MINI service standaard omvang	Uitvoeren
4/15/25	18,657	controle niveaus	Uitvoeren
4/15/25	18,657	klein materiaal	
4/15/25	18,657	ruitenwisserrubber vooraan	Vervangen
4/15/25	18,657	ruitenwisservloeistof	Bijvullen/-laden
4/15/25	18,657	service microfilter	Uitvoeren
4/15/25	18,657	service motorolie	Uitvoeren