MACADAM











Audi Q3 (UKL): 2BXN846

Vinnumber:	**WAUZZZF37N1106155**	Versionname:	**Q3 Sportback Bus. Attraction 35 1.5TFSi 150pk/cv 5p S-Tronic**
First Registrationdate:	**2/05/2022**	Fiscalpower:	
Expertise Mileage:	**35881**	Power Kw:	**110**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Hybrid Petrol**		
Maintenance	**OK**		
Maintenance	**in 12900 km**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**Tow bar collapsible**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**235/55/18/100 V**			
	Fr.L.	**Hankook: 5 mm**	Fr.R.	**Hankook: 5 mm**
	Re.L.	**Hankook: 5 mm**	Re.R.	**Hankook: 5 mm**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**5.0**
Tyre size FL	**235/55 R 18 100 V**
Tyre size FR	**235/55 R 18 100 V**
Tyre size RL	**235/55 R 18 100 V**
Tyre size RR	**235/55 R 18 100 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**260**
Tyre make FR	**260**
Tyre make RL	**260**
Tyre make RR	**260**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**

Seat cover RR, Deformed / Strained, Acceptable





Bumper moulding F, Scratch(es), Acceptable




Bumper R, Dent(s) and scratch(es), Repair and paint (complete)







Bumper moulding R, Scratch(es), Repair and paint (complete)








Wing RR, Scratch(es), Acceptable





Onderhoudshistorie van: WAUZZZF37N1106155

ALPHABET

Kenteken	2BXN846
Merk Model	Audi Q3 Sportback Bus. Attraction 35 1.5TFSi 150pk/cv 5p S-Tronic
Brandstofsoort	Benzine
Datum deel1	5/2/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
3/18/26	18,335	accu	Vervangen
3/18/26	18,335	batterij	Vervangen
3/18/26	18,335	klein materiaal	
3/18/26	18,335	koelwatervloeistof	Bijvullen/-laden
3/18/26	18,335	luchtfilter interieur	Vervangen
3/18/26	18,335	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
3/18/26	18,335	remvloeistof	Vervangen
3/18/26	18,335	ruitenwisserrubber achter	Vervangen
3/18/26	18,335	ruitenwisserrubber vooraan	Vervangen
3/18/26	18,335	ruitenwisservloeistof	Bijvullen/-laden
3/1/24	1,924	klein materiaal	Uitvoeren
3/1/24	1,924	luchtfilter interieur	Vervangen
3/1/24	1,924	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
3/1/24	1,924	ruitenwisservloeistof	Bijvullen/-laden