



IDENTIFICATION VEHICLE

Driver name:	HM Tongeren
Make:	AUDI
Model / version:	A3 SPORTBACK
Vin:	WAUZZZGY5PA024986
Plate:	
Mileage:	133968
First registration:	06/10/2022
Color:	Navarra Blue




ADDITIONAL INFORMATION



Category:
Transmission:
Interior color:
Metallic paint: ?
Type of lining:
Board computer reset: ?

DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	?
Maintenance book:	
Number of keys:	2
Original key:	✓

PICTURES





VIN INFORMATION

6 haut-parleurs
6 rapports
Diamètre avant 16
Largeur arrière 7,0
Hauteur avant 55
Indice de vitesse arrière V
Chauffage supplémentaire
Accoudoir central avant
1.00 litre
Euro 6
Rétroviseur intérieur jour/nuit
automatique
Volant cuir
Caméra avant

Téléphone
Matière : alliage
Diamètre arrière 16
Diamètre avant 16
Hauteur arrière 55
Largeur avant 205
Climatisation
Essence
81 kw
Métallisée vernissée
Siège avant gauche chauffant
Volant chauffant
Caméra arrière de recul

Boîte manuelle
Lettre repère (J)
Largeur avant 7,0
Diamètre arrière 16
Indice de vitesse avant V
Largeur arrière 205
Climatisation réfrigérant 1234YF
999 cm3
110 ch
Rétroviseur gauche asphérique
Sièges avant chauffants
Volant multifonction
Affichage lecture des panneaux de
signalisation

Appel de secours	Pare-brise teinté dégradé	Attelage avec boule amovible
Airbag passager	Airbag passager désactivable	Freinage d'urgence assistée autonome (urbain)
depuis 09.22	radio avec récepteur numérique	garnissage tissu Index
extincteur	système de gonflage des pneus	sidebag av/ar avec airbag pour la tête et airbag central av
réservoir à charbon actif (EVAP)	freins av 288x15	FREINS AR 272X10

EQUIPMENT

Board computer:	?	Central locking:	?
Compressor:	✓	Cruise control:	?
Gps:	?	Power steering:	?
Rear parking sensor:	?	Repair kit:	✓
Front seats heated:	?	Steering wheel:	?
Electric windows:	?	Climate control type:	
Headlighting type:		Tow bar type:	
Charging cables:	0	Fast charging cables:	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	6 mm			Summer		?
Front right	6 mm			Summer		?
Rear left	6 mm			Summer		?
Rear right	6 mm			Summer		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Bumper trim F	Grooved
3	Outside rear-view mirror housing L	Scratch(es)
4	Inner door sill FL	Dent(s) and scratch(es)
5	Bumper R	Scratch(es)
6	Tailgate / Boot	Scratch(es)
7	Door FR	Scratch(es)
8	Outside rear-view mirror housing R	Scratch(es)

Total: 7

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
2	Bodywork	Dent(s) and scratch(es)	✓	✗	✗

Total: 1

DAMAGES DETAILS


1 - Bumper trim F - Grooved



3 - Outside rear-view mirror housing L - Scratch(es)




4 - Inner door sill FL - Dent(s) and scratch(es)



5 - Bumper R - Scratch(es)



6 - Tailgate / Boot - Scratch(es)



7 - Door FR - Scratch(es)



8 - Outside rear-view mirror housing R - Scratch(es)





SIGNATURE
