



Volkswagen Golf (UKL): 2CFX616

Vinnumber:	WVWZZZCDZNW190783	Versionname:	Golf VIII Life 1.0TSi 110pk/cv 5p
First Registrationdate:	8/07/2022	Fiscalpower:	
Expertise Mileage:	59968	Power Kw:	81
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:	Petrol		
Maintenance	OK		
Maintenance	9500.0		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
Type of Maintenance book	Digital maintenance	Type of Tow bar	No Tow bar
Type of GPS storage	N.A.		

Tyres

	205/55/16/91 V			
Summer tyres:	Fr.L.	Nexen: 4 mm	Fr.R.	Nexen: 4 mm
	Re.L.	Nexen: 6 mm	Re.R.	Nexen: 6 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				205/55 R 16 91 V
Tyre size FR				205/55 R 16 91 V
Tyre size RL				205/55 R 16 91 V
Tyre size RR				205/55 R 16 91 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				1957072
Tyre make FR				1957072
Tyre make RL				1957072
Tyre make RR				1957072

Assistance equipment

Repair kit	Yes	Compressor	Yes
Seat cover RL, Stain, Cleaning			



Bumper F, Scratch(es), Repair and paint (complete)



Bonnet, Hail damage, Paintless dent repair (hail)



Alloy rim FL, Scratch(es), Acceptable



Outside rear-view mirror base L, Scratch(es), Acceptable



Wing RL, Scratch(es), Acceptable



Step L, Dent(s) and scratch(es), Spot repair



Boot lid covering R, Scratch(es), Smart repair



Bumper R, Scratch(es), Repair and paint (complete)





Rear wiper arm, Missing, Replace



Alloy rim RR, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Polish



Door FR, Scratch(es), Acceptable




Alloy rim FR, Scratch(es), Repair and paint (complete)







Outside rear-view mirror housing R, Scratch(es), Acceptable



Roof pillar R, Dent(s), Acceptable



Roof, Hail damage, Paintless dent repair (hail)



Kenteken	2CFX616
Merk Model	Volkswagen Golf VIII Life 1.0TSi 110pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	7/8/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
3/23/26	52,579	batterij	Vervangen
10/17/25	42,403	klein materiaal	
10/17/25	42,403	luchtfilter interieur	Vervangen
10/17/25	42,403	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
2/29/24	16,472	klein materiaal	
2/29/24	16,472	koelwatervloeistof	Bijvullen/-laden
2/29/24	16,472	ruitwisserrubber achter	Vervangen
2/29/24	16,472	ruitwisserrubber vooraan	Vervangen
2/29/24	16,472	ruitwisservloeistof	Bijvullen/-laden
2/29/24	16,472	Tussentijds onderhoud (vast interval)	Uitvoeren