



Peugeot 208: L628GD

Vinnumber:	VR3UHZKXZMT050922	Versionname:	e-208 50kWh 100kW Active Pack automaat
First Registrationdate:	15/07/2021	Fiscalpower:	
Expertise Mileage:	47947	Power Kw:	100
Bodytype:		Body colour	Noir Perla Nera metaallak
Gearbox:	Automatic	Paint type	Metalic
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Electric	Parking lot	460
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	No		

Options

Number of keys total	2	Rear parking sensors
Autom climate control		
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	195 / 55 / 16 / 87 / H / Aluminium	3,8 mm	Michelin	Summer
	Right	195 / 55 / 16 / 87 / H / Aluminium	3,8 mm	Michelin	Summer
Rear	Left	195 / 55 / 16 / 87 / H / Aluminium	4,2 mm	Michelin	Summer
	Right	195 / 55 / 16 / 87 / H / Aluminium	4,2 mm	Michelin	Summer

Assistance equipment

Number of charging cables (rapid charge)	1
--	----------

Interior, Stain, Cleaning



Wing RL, Scratch(es), Polish



Bonnet, Stone chip(s), Repair and paint (complete)



Windscreen, Stone chip(s), Windscreen repair



Wing RR, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Roof pillar R, Scratch(es), Repair and paint (complete)



Bumper R, Crack, Replace and paint



Bumper RM, Crack, Replace



Rear spoiler, Chemical polution, Polish



Roof, Scratch(es), Repair and paint (complete)



Kenteken	L628GD
Merk Model	Peugeot e-208 50kWh 100kW Active Pack automaat
Brandstofsoort	Elektrisch
Datum deel1	15-07-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
30-03-26	45.785	ABS module
30-03-26	45.785	Sensor ABS/ASR
20-03-26	45.605	Onderhoudsbeurt
20-03-26	45.605	Remvloeistof
20-03-26	45.605	Reparatie band(en)
20-03-26	45.605	Ruitenwisherblad(en) voorzijde
20-03-26	45.605	Sleutelbatterij
17-07-25	40.154	APK
04-10-24	32.615	Onderhoudsbeurt
04-10-24	32.615	Raam mechanisme
06-08-24	0	Accu
25-09-23	22.537	Onderhoudsbeurt
25-09-23	22.537	Remvloeistof
26-08-22	11.012	Onderhoudsbeurt