



## DS 7: GP-589-KG

|                         |                          |                         |                                                                               |
|-------------------------|--------------------------|-------------------------|-------------------------------------------------------------------------------|
| Vinnumber:              | <b>VR1JCYHZUPY540130</b> | Versionname:            | <b>DS DS 7 BlueHdi 130 Automatique BASTILLE VP [5P] bva 8-130CH-7cv (SUV)</b> |
| First Registrationdate: | <b>8/06/2023</b>         | Fiscalpower:            |                                                                               |
| Expertise Mileage:      | <b>131647</b>            | Power Kw:               | <b>96</b>                                                                     |
| Bodytype:               | <b>SUV</b>               | Body colour:            | <b>Black</b>                                                                  |
| Gearbox:                | <b>Automatic</b>         | Paint type:             | <b>Metallic</b>                                                               |
| Transmission:           | <b>Front</b>             | Interior colour:        | <b>Gold</b>                                                                   |
| Fueltype:               | <b>Diesel</b>            | Type of rims (mounted): | <b>Aluminium</b>                                                              |
| Engine functioning:     | <b>Yes</b>               | Dashboard color:        | <b>Black</b>                                                                  |
| Battery functioning:    | <b>Yes</b>               |                         |                                                                               |
| Vehicle running:        | <b>Yes</b>               |                         |                                                                               |
| Number of doors:        | <b>5</b>                 |                         |                                                                               |
| Number of seats:        | <b>5</b>                 |                         |                                                                               |
| Number head rests:      | <b>5</b>                 |                         |                                                                               |
| Type of rims (mounted): | <b>Aluminium</b>         |                         |                                                                               |
| Category:               | <b>Passenger Car</b>     |                         |                                                                               |

## Options

|                                |                              |                            |                     |
|--------------------------------|------------------------------|----------------------------|---------------------|
| Number of keys total           | <b>1</b>                     | Radio                      |                     |
| Number keys remote             | <b>1</b>                     | Central consol F           |                     |
| Windows electric F             |                              | Luggage cover              |                     |
| Cruise Control                 |                              | Headlights Xenon/LED/Laser |                     |
| Steering wheel multifunctional |                              | Front parking sensors      |                     |
| Steering wheel leather         |                              | Rear parking sensors       |                     |
| Type of climate control        | <b>Autom climate control</b> | Seat cover lining          | <b>Lining Other</b> |

## Tyres

|                       |       |               |       |                   |
|-----------------------|-------|---------------|-------|-------------------|
| 225/55/18/102 V       |       |               |       |                   |
| Winter tyres:         | Fr.L. | Michelin: 85% | Fr.R. | Michelin: 85%     |
|                       | Re.L. | Michelin: 50% | Re.R. | Michelin: 60%     |
| Tyre profile depth FL |       |               |       | 2.5               |
| Tyre profile depth FR |       |               |       | 2.5               |
| Tyre profile depth RL |       |               |       | 4.9               |
| Tyre profile depth RR |       |               |       | 4.2               |
| Tyre size FL          |       |               |       | 225/55 R 18 102 V |
| Tyre size FR          |       |               |       | 225/55 R 18 102 V |
| Tyre size RL          |       |               |       | 225/55 R 18 102 V |
| Tyre size RR          |       |               |       | 225/55 R 18 102 V |
| Tyre type FL          |       |               |       | Winter            |
| Tyre type FR          |       |               |       | Winter            |
| Tyre type RL          |       |               |       | Winter            |
| Tyre type RR          |       |               |       | Winter            |
| Tyre make FL          |       |               |       | 261               |
| Tyre make FR          |       |               |       | 261               |
| Tyre make RL          |       |               |       | 261               |
| Tyre make RR          |       |               |       | 261               |

## Assistance equipment

Remote ignition key (no insert), Missing, Repair/replace (lump sum)



Malfunction indicator, Blinking, Check



Seat cover FL, Burned, Replace



Floor mat F, Tear, Replace



Interior, Dirty, Cleaning



Interior covering B pillar L, Scratch(es), Repair/replace (lump sum)



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim RL bitone/polychrome, Scratch(es), Acceptable



Tyre FR, Out of tolerance, Replace



Tyre RR, Out of tolerance, Replace



Tyre RL, Out of tolerance, Replace



Tyre FL, Out of tolerance, Replace



Door RL, Dent(s), Repair and paint (complete)



Door FL, Scratch(es), Paint



Bumper moulding F, Scratch(es), Paint



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Deformed / Strained, Repair and paint (complete)



Bumper R, Scratch(es), Replace



Bumper moulding RL, Scratch(es), Replace





Roof, Dent(s) and scratch(es), Repair and paint (complete)



Historique Maintenance

Immatriculation: GP-589-KG Date de 1ère immatriculation: 08/06/2023

Modèle: DS 7 BlueHDi 130 Automatique BASTILLE VP [5P] bva 8-130CH-7cv (SUV)

| Date       | Kilométrage | Fournisseur                       | Descriptif                           |
|------------|-------------|-----------------------------------|--------------------------------------|
| 24/02/2026 | 115.271     | AUTOBERNARD ISERE                 | REVISION                             |
| 31/10/2025 | 101.034     | VOIRON DISTRIBUTION<br>AUTOMOBILE | DISQUES PLAQUETTES AR RPLT           |
|            | 0           |                                   | ESSAI                                |
| 08/09/2025 | 91.585      | C.B.B.                            | ADBLUE                               |
|            | 0           |                                   | BALAIS ESSUIE GLACE AV               |
|            | 0           |                                   | LIQUIDE DE FREIN                     |
|            | 0           |                                   | REVISION                             |
| 09/12/2024 | 64.004      | C.B.B.                            | REVISION ET CLIM ET AIR ET CARBURANT |
| 12/04/2024 | 30.357      | LE MANS MOTORS                    | REVISION                             |
|            | 0           |                                   | RECYCLAGE                            |