



Mercedes C-Klasse (KML): 2ANS069

Vinnumber:	W1K2052131G088639	Versionname:	C300de Break Business Solution 2.0d 306pk/cv 5p 9G-Tronic
First Registrationdate:	27/05/2021	Fiscalpower:	
Expertise Mileage:	113364	Power Kw:	143
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:	Hybrid Diesel		
Maintenance	NOT OK		
Maintenance	service A arrivé à échéance		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	225/45/18/95 W			
Summer tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				225/45 R 18 95 W
Tyre size FR				225/45 R 18 95 W
Tyre size RL				245/40 R 18 97 Y
Tyre size RR				245/40 R 18 97 Y
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		
Number of charging cables (rapid charge)	1		

Service, Maintenance, Check



Bumper F, Scratch(es), Repair and paint (complete)



Bumper moulding F, Scratch(es), Repair and paint (complete)



Windscreen, Bad repair, Replace



Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Wing FL, Scratch(es), Spot repair




Alloy rim RL polished, Scratch(es), Repair and paint (complete)



Wing RL, Dent(s), Acceptable




Door FL, Scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s), Acceptable



Kenteken	2ANS069
Merk Model	Mercedes C300de Break Business Solution 2.0d 306pk/cv 5p 9G-Tronic
Brandstofsoort	Diesel
Datum deel1	5/27/21

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
7/23/25	91,425	klein materiaal	
7/23/25	91,425	mercedes assyst b	Uitvoeren
7/23/25	91,425	remvloeistof	Vervangen
7/23/25	91,425	ruitenwisserrubber achter	Vervangen
7/23/25	91,425	ruitenwisserrubber vooraan	Vervangen
7/23/25	91,425	stoffilter (motor compartiment)	Vervangen
4/2/25	84,589	extra batterij	Vervangen
7/11/24	70,745	brandstoffilter	Vervangen
7/11/24	70,745	dakgel. smeren	Uitvoeren
7/11/24	70,745	klein materiaal	Uitvoeren
7/11/24	70,745	luchtfilter	Vervangen
7/11/24	70,745	mercedes assyst a	Uitvoeren
7/13/23	47,792	klein materiaal	Uitvoeren
7/13/23	47,792	mercedes assyst b	Uitvoeren
7/13/23	47,792	remvloeistof	Vervangen
6/22/22	23,759	klein materiaal	
6/22/22	23,759	mercedes assyst a	Uitvoeren