



**VOLKSWAGEN TIGUAN: 1**

Vinnumber:	<b>WVGZZZ5NZLW896011</b>	Versionname:	<b>1.5 TSI ACT OPF 110kW DSG IQ.Drive</b>
First Registrationdate:	<b>24/06/2020</b>	Fiscalpower:	
Expertise Mileage:	<b>82817</b>	Power Kw:	<b>110</b>
Bodytype:		Body colour:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>3501</b>
Fueltype:	<b>Petrol</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Registration Certificate Home (BE):	<b>No</b>		

**Options**

Number of keys total:	<b>1</b>	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Seats F heated:		Type of Tow bar:	<b>No Tow bar</b>
Radio multimedia:			
Type of headlighting:	<b>Headlighting Halogen</b>		
Type of GPS:	<b>GPS big screen color</b>		
Type of Lining:	<b>Lining fabrics</b>		
Type of climate control:	<b>Autom climate control</b>		
Type of GPS storage:	<b>SD present</b>		

**Limited Technical Inspection**

**Tyres**

255/55/19/100 V				
Summer tyres:	Fr.L.	<b>Bridgestone: 2 mm</b>	Fr.R.	<b>Bridgestone: 2 mm</b>
	Re.L.	<b>Bridgestone: 4 mm</b>	Re.R.	<b>Bridgestone: 4 mm</b>
Tyre profile depth FL				<b>2.0</b>
Tyre profile depth FR				<b>2.0</b>
Tyre profile depth RL				<b>4.0</b>
Tyre profile depth RR				<b>4.0</b>
Tyre size FL				<b>255/55 R 19 100 V</b>
Tyre size FR				<b>255/55 R 19 100 V</b>
Tyre size RL				<b>255/55 R 19 100 V</b>
Tyre size RR				<b>255/55 R 19 100 V</b>
Tyre type FL				<b>Summer</b>
Tyre type FR				<b>Summer</b>
Tyre type RL				<b>Summer</b>
Tyre type RR				<b>Summer</b>
Tyre make FL				<b>255</b>
Tyre make FR				<b>255</b>
Tyre make RL				<b>255</b>
Tyre make RR				<b>255</b>

**Assistance equipment**

Repair kit:	<b>Yes</b>	Compressor:	<b>Yes</b>
Number of charging cables (normal):	<b>0</b>		
Number of charging cables (rapid charge):	<b>0</b>		

Total cost ex VAT:	<b>604,67</b>
Ignition key, Missing, Replace:	<b>350,09</b>



Door FL, Dent(s) and scratch(es), Acceptable 0,00



Door RL, Dent(s) and scratch(es), Acceptable 0,00



Tailgate / Boot, Dent(s), Paintless dent repair 127,29



Door FR, Dent(s), Acceptable 0,00



Door RR, Dent(s), Paintless dent repair 127,29



Wing FR, Dent(s), Acceptable 0,00



Bodywork, Not original part, Remove lettering 0,00

