MACADAM








CITROËN C3 Origin: 4255-MTM

Vinnumber:	**VF7SXYHTURT091488**	Versionname:	**Citroen BlueHDi 75KW (100CV) Plus berlina con portón 75kW 5P manual**
First Registrationdate:	**8/08/2024**	Fiscalpower:	
Expertise Mileage:	**69038**	Power Kw:	
Bodytype:	**Berline**	Body colour	**White**
Gearbox:	**MAN 6 VIT**	Type of rims (mounted)	**Steel**
Transmission:			
Fueltype:	**Diesel**		
Engine functioning	**Yes**		
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Steel**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**1**	Luggage cover	
Number keys remote	**1**		
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**205/55/16/94 V**			
	Fr.L.	**Michelin: 5 mm**	Fr.R.	**Goodyear: 5 mm**
	Re.L.	**Goodyear: 5 mm**	Re.R.	**Goodyear: 5 mm**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**5.0**
Tyre size FL	**205/55 R 16 94 V**
Tyre size FR	**205/55 R 16 94 V**
Tyre size RL	**205/55 R 16 94 V**
Tyre size RR	**205/55 R 16 94 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**261**
Tyre make FR	**259**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**

Boot lid covering R, Scratch(es), Smart repair




Interior, Dirty, Cleaning





Ignition key, Missing, Repair/replace (lump sum)




Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)




Tyres, No damage, Check










ALPHABET

Datos del vehículo

Marca	CITROËN	Matrícula	4255-MTM
Modelo	C3 Origin	VIN	VF7SXYHTURT091488
Versión	Citroen BlueHDi 75KW (100CV) Plus berlina con portón 75kW 5P manual		

Histórico

Fecha	Descripción	Kilómetros	Taller
23/07/2025	Bajos sin perdida de liquidos | Aceite motor - - - ALP EURO | Arandela / tapón cárter - FEBI BILSTEIN - Rec.Plat. EuroTaller - GOMA | Filtro aceite - MANN-FILTER - Rec.Plat. EuroTaller | Filtro antipolen - MANN-FILTER - Rec.Plat. EuroTaller - CARBON ACTIVO - Nueva | Líquido lavaparabrisas - CONCENTRADO - Nueva | Rellenar niveles | Serv inspección 30000 KM | Sustituir Filtro antipolen | Sustituir Rellenar niveles | Tasa de gestión de aceites usados	32083	TALLERES EÑE, S.L.
12/02/2026	Reparación pinchazo	44108	Ángel David Mateo Fidalgo
25/02/2026	Aceite motor - - - ALP EURO | Importe de pago por uso | Líquido frenos - IAM | Líquido lavaparabrisas - CONCENTRADO - Nueva | Rellenar niveles | Serv inspección 2º año | Sustituir Líquido frenos | Sustituir Rellenar niveles | Tasa de gestión de aceites usados	52200	TALLERES EÑE S.L.
20/02/2026	Ecotasa - N2 | Goodyear / 205/55R16 94V EFFIGRIP PERF 2 XL OE1 | Sustitucion y kit de montaje	52202	Ángel David Mateo Fidalgo

Fecha	Descripción	Kilómetros	Taller