

» Overview

Order number: 1002421375
Order completed: 22.04.2026 12:39
Report number: 10487161
VIN: WVGZZZ5N1PM015238



Front Left 3/4



Rear Right 3/4



Mileage

» Vehicle Data

Vehicle category:	Passenger Car
Vehicle type:	SUV
Make:	Volkswagen
Model:	Tiguan
Manufacturers and type code:	0603 / CNG
Date of first registration:	06.03.2023
Mileage:	79,686 km
Proof of mileage:	ReadOff
Exterior colour:	Deep Black Perleffekt
Roof colour:	Deep Black Perleffekt
Propulsion:	4 Wheel-drive
Fuel:	Petrol
Engine size (cc):	1,984 ccm
Performance:	180 kW (245 PS)
Length:	
Height:	
Width:	
Permitted total weight:	
Wheelbase:	
Number of powered axles:	2
Cylinders:	4
Euronorm:	Euro 6
Number of doors:	4
Number of seats:	5
Gearbox:	Automatic 7-speed
Upholstery type:	Lining semi-leather
Interior colour:	Titanschwarz-Kristallgrau/Titanschwarz/ Schwarz/Titanschwarz
Number of keys:	2

» Documents & Maintenance

Statutory inspection date:	03.2026
Registration certificate available:	Yes
Registration certificate received:	Yes
License plate:	None
Maintenance book:	Digital
Maintenance:	Not testable
Maintenance last date:	
Maintenance last mileage:	
Remainder until next maintenance:	7,300 KM

<p>"Misano" 8.5J x 20, Volkswagen R, AirStop® tires 255/40 R20</p> <p>12 V outlet in center console in rear and in luggage compartment</p> <p>2 LED reading lights in front and 2 in rear</p> <p>2 USB-C ports in the front, 1 USB-C charging socket on the center console in the rear</p> <p>230-V outlet</p> <p>3 head restraints in rear</p> <p>30-color ambient lighting</p> <p>3-point seat belt for center rear seat</p> <p>3-point seat belts in front with height adjustment and seat belt pretensioners</p> <p>3-point seat belts with seat belt pretensioners for the outer rear seats</p> <p>4 alloy wheels "Misano" 8.5J x 20, Volkswagen R</p> <p>4-cylinder SI engine 2.0 I</p> <p>4-cylinder SI engine 2.0 I TSI, 180 kW</p> <p>7-speed automatic or DSG for four-wheel drive note: family EDF</p> <p>Activated carbon canister (Evaporative Emission Control System (EVAP))</p> <p>Active climate seats in front</p> <p>Adaptive Chassis Control DCC incl. Driving Mode Selection</p> <p>Adaptive Cruise Control ACC stop & go incl. speed limiter</p> <p>Additional luggage compartment light, removable and usable as a flashlight</p> <p>Advanced high-beam control Dynamic Light Assist for LED matrix headlamps</p> <p>Air Care Climatronic 3 zone automatic climate control w/ allergen filter, enhanced air filter a. controls in rear</p> <p>AirStop® tires 255/40 R20</p> <p>Alternator 140 A</p> <p>Anti-theft alarm system with interior monitoring, backup horn and towing protection</p> <p>Anti-theft alarm system with SAFELOCK</p> <p>App-Connect incl. App-Connect Wireless for Apple CarPlay and Android Auto</p> <p>Area View including rear view camera system</p> <p>Aspherical exterior mirror on driver side</p> <p>Auto-dimming interior rearview mirror</p> <p>Automatic headlight control with LED separate daytime running light and exit and entry lighting</p> <p>Automatically-heated washer nozzles in front</p> <p>Autonomous Emergency Braking Front Assist (for Adaptive Cruise Control ACC up to 210 km/h)</p> <p>Battery 380 A (68 Ah)</p> <p>Black headliner</p> <p>Black rear spoiler in "R" style</p> <p>Bracket for first aid kit and warning triangle</p> <p>Bumpers and sill extension in "R" style, Black wheel housing flaring</p>	<p>Business Premium package incl. navigation system</p> <p>Carpet mats in front and rear with decorative stitching in Gray</p> <p>Carrier frequency 433.92 MHz-434.42 Mhz</p> <p>Center armrest in front</p> <p>Chrome moldings on the side windows</p> <p>CO2 variant</p> <p>Cornering light and poor weather light</p> <p>Dark Red LED rear combination lamps</p> <p>Decorative inserts "Carbon Gray" for dashboard and front door trim panels</p> <p>Digital radio reception DAB+</p> <p>Disc brakes in front</p> <p>Disc brakes in rear</p> <p>Diversity antenna for FM reception</p> <p>Door and side trim panel in foam film, insert in leatherette</p> <p>Driver alert system</p> <p>Driver+front passenger airbag with fr. passenger airbag deactivation, incl. knee airbag on driver+fr. passenger side</p> <p>Driving on the right</p> <p>Dual-clutch transmission DSG DQ381</p> <p>Dynamic headlight range control, with dynamic cornering light</p> <p>Dynamic Road Sign Display</p> <p>Easy Open & Close - sensor controlled luggage compartment opening and closing with remote unlocking</p> <p>Easy Open & Close package with SAFELOCK</p> <p>ECO function</p> <p>Electromechanical parking brake with Auto Hold function</p> <p>Electronic Stability Control w/ driver steering recommendation, ABS, ASR, EDL, EDTC and trailer stabilization</p> <p>Elimination of nameplate for engine designation on luggage compartment lid</p> <p>Emergency call service; no registration required, service is activated upon delivery</p> <p>Emission standard EU6 AP</p> <p>Equipment options subset for Germany</p> <p>Exterior mirror housings painted in Silver</p> <p>Exterior mirrors, power-adjustable, folding and heated, with memory feature and surround lighting</p> <p>First aid kit, warning triangle and safety vest</p> <p>Folding trailer hitch, with electric release</p> <p>Four-wheel drive 4MOTION</p> <p>Front scuff plates in aluminum, with "R-Line" logo</p> <p>Front seats with power adjustment, with memory feature; front seat convenience entry function on driver side</p> <p>Front stabilizer bar</p> <p>Front-end underbody cladding incl. stone guard</p> <p>Fuel system for fuel-injected SI engine</p>
--	---

Gearshift knob in leather	Non-folding front passenger seat backrest
Green heat-insulating glass windows on sides and in rear	Non-smoker's package: Storage compartment and 12 V outlet in front
Harman Kardon sound system, 8+1 speakers, 480 W total power output, digital 16-chan. amplifier, subwoofer	Not hot country
Hatchback	Online service, with OCU, with head unit coding, without engine immobilizer interconnection
Head-up Display	Operating permit, alteration
Heated (without wires) and infrared-reflecting windshield	Overhead storage compartments
Heated front and outer rear seats	Parking heater and ventilation with radio remote control and timer
Hill Descent Control	Parking heater and ventilation with radio remote control and timer
Illuminated molding between headlamps	Part set without country-specific prescriptive standard
Illuminated vanity mirrors in sun visors	Pedals in brushed stainless steel
Initial standard fuel filling	Pedestrian Monitoring
Inserts of front seats and outer rear seats in perforated leather "Vienna", "R-Line" logo in front	Power-adjustable lumbar supports in front
Instrument cluster with electronic speedometer, odometer and trip odometer, tachometer	Premium comfort seats in front
IQ.DRIVE assistance systems package incl. semi-automated vehicle assistance in a medical emergency Emergency Assist	Preparation for We Connect and We Connect Plus
IQ.LIGHT - LED Matrix headlamps with LED sep. daytime running light, dynamic cornering light and dynamic turn signal	Proactive passenger protection system in combination with Front Assist and Side Assist
ISOFIX anchorage points for mounting 2 child seats on rear seats, also for i-Size child seats	Progressive steering
Keyless locking and starting system Keyless Access with SAFELOCK	Protective side molding
Laminated safety glass windshield, heated (without wires) and infrared-reflecting	Radiator grille
Lane change system Side Assist	Radio
Leather package "Vienna", Volkswagen R, incl. front seats with memory feature	Rain sensor
Leather-wrapped multi-function sports steering wheel, heated, with touch control and shifting paddles	Rear bench seat asymm. split folding, longitudinally movable and folding with load-through hatch and center armrest
LED license plate lighting	Rear fog lamp
Left-hand drive	Rear shock absorption
License plate carrier in front and rear (ECE)	Rear stabilizer bar
Light unit in front footwell	Refrigerant R1234yf
LongLife Service Regime	Regional code " ECE " for radio
Luggage compartment cover	Remote unlocking for rear seat backrest
Luggage compartment floor adjustable in 2 heights	Right exterior mirror, convex
Luggage net	R-line equipment
Manual in German (Germany)	Safety-optimized front head restraints, longitudinally and height adjustable
Mexico manufacturing sequence	Service indicator 30 000 km or 2 years (variable)
Mobile phone interface "Comfort" with inductive charging feature	Shock absorption in front
Multi-color Digital Cockpit Pro, selection of different info profiles possible	Side airbags for outer seats of 2nd row of seats, incl. side airbags in front and curtain airbag system
Multifunction camera	Silver-anodized roof rails
Navigation system "Discover Pro" incl. Streaming & Internet	Special identification label for EC for M1 passenger vehicles
Navigation system "Discover Pro" incl. Streaming & Internet	Standard battery/alternator capacity
Net partition	Standard climatic zones
No special edition	Standard curb weight range
No special purpose vehicle, standard equipment	Standard engine starter
	Standard paint coating

Start-stop system with regenerative braking Without vehicle inlet

Storage compartment with cover on dashboard

Styling elements on the power mirror switch, window regulator switches and door pulls

Suspension range 06 installation control only, no requirement forecast

Textile luggage compartment trim

Tire Mobility Set: 12-volt compressor and tire sealant

Tire Pressure Monitoring System

Tires without specification of tire brand

Tool kit

Trailer maneuvering system Trailer Assist incl. Park Assist and Park Distance Control

Travel Assist, Lane Assist and Emergency Assist

Trims for alloy wheels

Two-tone horn

Type approval country Germany

Vehicle class differentiation -55N-

Vehicles with special upgrade measures

Voice control

VWD model year change

Warning lamp for washer fluid level

Warning signal and warning lamp for front and rear seat belts not fastened

Weight range 17 installation control only, no requirement forecast

Wheel locks with extended theft protection

Wheelbase

Winter package, additionally with heated outer rear seats

With additional transport protection measures

Without additional tires

Without alternative drive system

Without country code (no DVD player in the vehicle)

Without decals and emblems

Without delivery equipment

Without drawers under front seats

Without electronic steering column lock

Without fire extinguisher

Without folding table on front seat backrest

Without garage door opener

Without headlamp washer system

Without heat accumulator/auxiliary heater

Without roof insert (standard roof)

Without second battery

Without special body measures

Without storage compartment package/box

» Tyres

MOUNTED TYRES

There are currently one or more wheel sets on/in the vehicle that are not included in the scope of delivery.

Make	Location	Position	Type	Rim	Dimensions	Profile depth
Continental	Front	Left	Winter	Aluminium	235/55 R 18 100 H	5.0 mm
Continental	Front	Right	Winter	Aluminium	235/55 R 18 100 H	5.0 mm
Continental	Rear	Left	Winter	Aluminium	235/55 R 18 100 H	7.0 mm
Continental	Rear	Right	Winter	Aluminium	235/55 R 18 100 H	7.0 mm

Roadworthy: Yes

UNMOUNTED TYRES

Make	Location	Position	Type	Rim	Dimensions	Profile depth
Continental			Summer	Aluminium	255/40 R 20 101 V	6.0 mm
Continental			Summer	Aluminium	255/40 R 20 101 V	6.0 mm
Continental			Summer	Aluminium	255/40 R 20 101 V	6.0 mm
Continental			Summer	Aluminium	255/40 R 20 101 V	6.0 mm

Permitted: Yes

Roadworthy: No

SPARE/EMERGENCY TYRE & ACCESSORIES

Toolkit present: Yes

Repair kit present: Yes

Repair kit expiration date: 05.2026

Compressor present: Yes

» Devaluation Factors

Nr	Location	Damage type	Repair type
1	Tailgate / Boot	Scratch(es)	Paint
2	Bonnet	Rust	Paint
3	Door RR	Scratch(es)	Paint
4	Preparationtime metal painting	Paint preparation	Execute
5	Additional tyre(s)	Tear	Replace
6	Additional tyre(s)	Tear	Replace
7	Additional tyre(s)	Tear	Replace
8	Additional rim(s) polished	Scratch(es)	Visual depreciation
9	Additional rim(s) polished	Scratch(es)	Visual depreciation
10	MOT certificate	Expired	Renew
11	Side wall RR	Dent(s)	Paintless dent repair
12	Floor mat(s)	Worn	Replace
13	Warning indicator tire pressure	Lights up	Diagnosis Damage extension possible
14	Ignition key	Not functioning (well)	Diagnosis Damage extension possible

» Usage Damages

Nr	Location	Damage type	Repair type
1	Bonnet	Repaired	Acceptable
2	Bumper F	Repaired	Acceptable
3	Bumper F	Scratch(es)	Acceptable
4	Door RL	Dent(s)	Acceptable
5	Door trim FL	Scratch(es)	Acceptable
6	Inner door sill RL	Scratch(es)	Acceptable
7	Outside rear-view mirror housing L	Scratch(es)	Acceptable
8	Door FL	Dent(s)	Acceptable
9	Bumper R	Scratch(es)	Acceptable
10	Door FR	Dent(s)	Acceptable
11	Wing FR	Dent(s)	Acceptable
12	Brake discs front	Deviation from delivery condition/scope	Acceptable
13	Alloy rim FR	Scratch(es)	Acceptable
14	Additional rim(s) polished	Scratch(es)	Acceptable
15	Door FL	Scratch(es)	Acceptable

» Commercial devaluation

Accidental vehicle:	Yes
Known previous damages:	Yes
Previous damages detectable:	Yes
Repainting present:	Yes
Paint thickness measurement performed:	Yes - with abnormalities/deviations

Nr	Location	Damage	Repair type	Repair cost
1	Other	Fully comprehensive harm		€ 9,471.28
Total without VAT:				€ 9,471.28

PAINTTHICKNESS MEASUREMENT RESULTS

Part	Paint (µm)
Paint thickness Wing FL (µm)	174.0
Paint thickness Wing FR (µm)	185.0

At least 3 measurements were carried out per component.

» Notes On The Assessment

Details of the assignment and the scope of the assessment:

The order was placed to prepare a condition report on the described vehicle.

The vehicle condition assessment was carried out in accordance with the order on the basis of the standards for vehicle assessments specified by the client. The expert makes the findings in the individual case on the basis of his own expertise and at his own expert discretion.

Vehicle identification:

WVGZZZ5N1PM015238

VIN checked and matches documentation

Vehicle condition:

Dirty

Inspection condition:

Restricted

Lifting platform/lifting equipment used:

Yes

Testdrive carried out:

No

Engine test carried out:

Yes

» Remarks

This copy was generated electronically. It is valid without an original signature.

Additional notes on the condition report:

(22.04.2026 12:39) Die zum Besichtigungszeitpunkt montierten Winterräder gehören laut Ausstattung nicht zum Fahrzeug und wurden daher nicht mit bewertet.

» Commercial Pictures



Front Left 3/4



Front Right 3/4



Rear Left 3/4



Rear Right 3/4



Mileage



Tools



Sill outer L




Sill outer R



Chassis nr



Wheel FL



Wheel FR



Wheel RL



Wheel RR



Additional wheel 1



Additional wheel 2



Additional wheel 3




Additional wheel 4



Central console




Engine compartment



Documents



Interior arrangement



Registration Certificate



Tyres in vehicle




Towbar



Paint thickness Wing FL



Paint thickness Wing FR



History Maintenance



Interior - front



Interior - rear



Tirefit expiration date



Underbody scan




GPS/Radio

» Devaluation Damages

DEVALUATION FACTORS

1 - Tailgate / Boot - Scratch(es) - Paint



2 - Bonnet - Rust - Paint

Comment

Erhöhte Steinschlagdichte.



3 - Door RR - Scratch(es) - Paint



4 - Preparationtime metal painting - Paint preparation - Execute

5 - Additional tyre(s) - Tear - Replace

Comment	Flanke beschädigt
---------	-------------------



6 - Additional tyre(s) - Tear - Replace

Comment	Flanke beschädigt
---------	-------------------




7 - Additional tyre(s) - Tear - Replace

Comment	Flanke beschädigt
---------	-------------------



8 - Additional rim(s) polished - Scratch(es) - Visual depreciation

Comment	Felge UVP netto 897,04€ - Optische Wertminderung
---------	--



9 - Additional rim(s) polished - Scratch(es) - Visual depreciation

Comment



Felge UVP netto 897,04€ - Optische Wertminderung




10 - MOT certificate - Expired - Renew



11 - Side wall RR - Dent(s) - Paintless dent repair



12 - Floor mat(s) - Worn - Replace



13 - Warning indicator tire pressure - Lights up - Diagnosis
Damage extension possible



14 - Ignition key - Not functioning (well) - Diagnosis
Damage extension possible

Comment

1 Funkfernbedienung der Fahrzeugschlüssel ohne Funktion, Schlüsselbatterie erneuern




USAGE DAMAGES

1 - Bonnet - Repaired - Acceptable

Comment

Motorhaube augenscheinlich nachlackiert/ Befestigungsschrauben mit Lackbeschädigung



2 - Bumper F - Repaired - Acceptable

Comment

Frontstoßfängerverkleidung augenscheinlich nachlackiert



3 - Bumper F - Scratch(es) - Acceptable



4 - Door RL - Dent(s) - Acceptable



5 - Door trim FL - Scratch(es) - Acceptable




6 - Inner door sill RL - Scratch(es) - Acceptable





7 - Outside rear-view mirror housing L - Scratch(es) - Acceptable



8 - Door FL - Dent(s) - Acceptable




9 - Bumper R - Scratch(es) - Acceptable	
Comment	schleifen und polieren



10 - Door FR - Dent(s) - Acceptable	
-------------------------------------	--



11 - Wing FR - Dent(s) - Acceptable	
-------------------------------------	--



12 - Brake discs front - Deviation from delivery condition/scope - Acceptable	
---	--

Comment	Bremsbeläge nahe Verschleißkontakt, Bremsscheiben mit Gratbildung / nahe der Verschleißgrenze.
---------	--





13 - Alloy rim FR - Scratch(es) - Acceptable	
--	--

Comment	LM-Felge der Winterräder vorne rechts verschrammt, ohne Berechnung da die Winterräder laut Ausstattung nicht zum Fahrzeug gehören.
---------	--



14 - Additional rim(s) polished - Scratch(es) - Acceptable



15 - Door FL - Scratch(es) - Acceptable

