



OPEL GRANDLAND X

Vinnnumber:	W0VZCYHZ9M6819842	Versionname:	1.5 Turbo D D S/S MT6 Elegance
First Registrationdate:	12/04/2021	Fiscalpower:	
Expertise Mileage:	73689	Power Kw:	96
Bodytype:		Body colour:	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	3710
Fueltype:	Diesel		
Maintenance:	OK		
Maintenance:	25820.0		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Rear parking sensors:	
Steering wheel multifunctional:		Type of Tow bar:	Tow bar removable
Radio multimedia:			
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Autom climate control		
Type of GPS storage:	HD		

Limited Technical Inspection

Tyres

225/55/18/102 Y				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/55 R 18 102 Y
Tyre size FR				225/55 R 18 102 Y
Tyre size RL				225/55 R 18 102 Y
Tyre size RR				225/55 R 18 102 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT	854,20
Bonnet, Chemical polution, Repair and paint (complete)	406,19



Alloy rim FL polished, Scratch(es), Acceptable 0,00



Alloy rim RL polished, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Spot repair 148,33



Alloy rim RR polished, Scratch(es), Repair and paint (complete) 204,21




Wing RR, Dent(s), Paintless dent repair 95,47



Step R, Scratch(es), Acceptable 0,00



Door FR, Scratch(es), Acceptable 0,00



Outside rear-view mirror base R, Scratch(es), Acceptable 0,00



Alloy rim FR polished, Scratch(es), Acceptable 0,00

