



VOLKSWAGEN Passat: 1954-MBX

Vinnumber:	WVWZZZ3CZPE011634	Versionname:	Variant Executive 2.0 TDI 110kW DSG familiar
First Registrationdate:	26/10/2022	Fiscalpower:	110kW 5P automática
Expertise Mileage:	185272	Power Kw:	
Bodytype:	Break	Body colour:	White
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:			
Fueltype:	Diesel		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	No		

Options

Number of keys total	2	Central consol F
Number keys remote	2	Luggage cover
GPS big screen color		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		Roof bar black
Cruise Control		
Steering wheel multifunctional		
Steering wheel leather		
Radio multimedia		
Type of climate control	Autom climate control	

Tyres

	215/55/17/94 V			
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				215/55 R 17 94 V
Tyre size FR				215/55 R 17 94 V
Tyre size RL				215/55 R 17 94 V
Tyre size RR				215/55 R 17 94 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit	No
Boot lid covering R, Broken, Replace	



Registration document, Missing, Repair/replace (lump sum)



Alloy rim FL bitone/polychrome, Scratch(es), Acceptable



Bumper F, Scratch(es), Repair and paint (complete)



Windscreen, Stone chip(s), Forfeit



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Wing FR, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)



Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Tyre repair kit, Missing, Repair/replace (lump sum)



Bumper spoiler Rear, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Tyres, No damage, Check



Datos del vehículo

Marca

Modelo

Versión

Matrícula

VIN

Histórico

Fecha	Descripción	Kilómetros	Taller

Datos del vehículo

Marca

Modelo

Versión

Matrícula

VIN

Histórico

Fecha	Descripción	Kilómetros	Taller