APPRAISAL REPORT



VEHICLE IDENTIFICATION

Driver name:	ASSE I
Make:	BMW
Model / version:	2 SERIES ACTIVE TOURER
Wine:	WBA2X910107K06956
Plate:	2BBX239
Mileage:	228488
First registration:	24/09/2021
Color:	Mineral Grey

ADDITIONAL INFORMATION


Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?


DOCUMENTS


Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✗
Maintenance book	
Number of keys:	2
Original key:	✓

PICTURES


























































WINE INFORMATION

Radio	Navigation system	Manual transmission
6 reports	LED spotlights	Equipment Advantage
Material: alloy	Reference letter (J)	Front diameter 16
Rear diameter 16	Front width 7.0	Rear width 7.0
Front diameter 16	Rear diameter 16	Front height 60
Rear height 60	Forward speed index H	Rear speed rating H
Front width 205	Rear width 205	Dual-zone automatic climate control
Air conditioning refrigerant 1234YF	Front center armrest	Essence
1499 cm3	1.50 liters	80 kW
109 hp	Glazed mineral	Automatic day/night interior rearview mirror
Heated front left seat	Heated front seats	Leather trim

Leather steering wheel	Sports steering wheel	Multifunction steering wheel
Front parking assistance	Rear parking assistance	Parking assistance
Front camera	Automatic distance control	Electrically operated trunk opening
Emergency call	rain sensor windshield wiper	Tow hitch with removable ball
Fixotoit	Pedestrian protection	Autonomous emergency braking assistance (urban)
Forward collision warning	Tire pressure check	since 08.21
large capacity fuel tank	additional standard RDE	extended CO2 measures
Teleservices	DAB tuner	adjustable rear seats
storage pack	anti-theft wheel bolts	dark matte Oxyx silver interior inserts
Europe-specific		

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	✓	**Cruise control:**	?
GPS:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	✓
Heated front seats:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlight type:		**Tow bar type:**	
Charging cables:	0	**Fast charging cables:**	0

TIRES

Position	Depth	Brand	Dimensions	Kind	Rims	Runflat
Front left	3 mm			Summer	Aluminum	?
Front right	3 mm			Summer	Aluminum	?
Rear left	3 mm			Summer	Aluminum	?
Rear right	3 mm			Summer	Aluminum	?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Rental	Damage type
2	Door RL	Scratches
3	Bumper R	Scratches
4	Alloy rim FR	Scratches

Total: 3

ACCEPTABLE / NOT TO BE INVOICED

#	Rental	Damage type	Renta®	Repaired	Already invoiced
1	Bodywork	Damaged	✓	✗	✗

Total: 1

DAMAGE DETAILS

2 - Door RL - Scratch(es)





3 - Bumper R - Scratches






4 - Alloy rim FR - Scratch(es)








1 - Bodywork - Damaged - Renta®











SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

06/11/2026 08:59

