DEKRA

DEKRA Automotive Solutions

Condition Report

Vehicle details

VIN	ZAC5JACL1 SJL77139	Mileage	29 190 km	Engine (Fuel) Type	Petrol
Licence Plate		Registration date	09/05/2025	Engine size	1199
Brand	JEEP	Fuel level		Transmission	-
Model	Avenger-2023	Car type	PC	Gears	-
Body Type	-	Number of seats	-	Condition of the car	Unknown
Doors	5	Exterior Color	Gris		

Inspection Details

Inspection date	08/10/2026	Inspection loc.	AVIS Own Risk - Parc AVIS	Fleet owner	AVIS Own Risk Belgique















Other technical information

Emergency compressor kit	✔
Refill emergency kit	✔

Tyres

Goodyear 215/60/17 V All seasons 4.0 mm

Goodyear 215/60/17 V All seasons 4.0 mm





Goodyear 215/60/17 V All seasons 5.0 mm

Goodyear 215/60/17 V All seasons 5.0 mm

Damages

1



Part	Door
Position	Front left
Damages	Dented
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	49.00€

2



Part	Door
Position	Front left
Damages	Stone impact
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	30.00€

3



Part	Wing moulding
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Replace
Net cost (Excluding VAT)	102.39€

4



Part	Unpainted bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Replace
Net cost (Excluding VAT)	398.77€

DEKRA

DEKRA Automotive Solutions

Condition Report

5		Part	Bumper	**6**	
		Position	Front left		
		Damages	Scratched		
		Severity	-		
		Repair mode	Smart Repair		
		Net cost (Excluding VAT)	90.00€		
7		Part	Door	**8**	
		Position	Front right		
		Damages	Dented		
		Severity	-		
		Repair mode	Repair		
		Net cost (Excluding VAT)	428.13€		
9		Part	Wing moulding	**10**	
		Position	Front right		
		Damages	Dented		
		Severity	-		
		Repair mode	Replace		
		Net cost (Excluding VAT)	102.39€		

Summary Inspection

Net Price (Exclusing VAT)	1,516.41€