



DACIA Duster: 0497-MCK

Vinnumber:	VF1HJD40569625093	Versionname:	Comfort Blue dCi 85kW (115CV) 4X4 todoterreno
First Registrationdate:	23/11/2022	Fiscalpower:	85kW 5P manual
Expertise Mileage:	232591	Power Kw:	
Bodytype:	Off-road	Body colour	White
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:			
Fueltype:	Diesel		
Engine functioning	Yes		
Battery functioning	Yes		
Vehicle running	Yes		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	No		

Options

Number of keys total	1	Luggage cover
Number keys remote	1	Rear parking sensors
Windows electric F		Roof bar black
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Steering wheel leather		
Radio multimedia		
Type of climate control	Manual climate control	

Tyres

	215/65/16/102 H			
Winter tyres:	Fr.L.	Cooper: 3 mm	Fr.R.	Cooper: 3 mm
	Re.L.	Cooper: 7 mm	Re.R.	Cooper: 7 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				7.0
Tyre profile depth RR				7.0
Tyre size FL				215/65 R 16 102 H
Tyre size FR				215/65 R 16 102 H
Tyre size RL				215/65 R 16 102 H
Tyre size RR				215/65 R 16 102 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				1957075
Tyre make FR				1957075
Tyre make RL				1957075
Tyre make RR				1957075

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Registration document, Missing, Repair/replace (lump sum)



Ignition key, Missing, Repair/replace (lump sum)



Interior, Not original part, Acceptable




Interior, Dirty, Cleaning



Backrest cover FL, Hole, Replace



Backrest cover FR, Hole, Replace



Boot lid covering R, Scratch(es), Replace



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Repair and paint (complete)



Wheel bolt cover FL, Missing, Replace



Bumper F, Not original part, Acceptable



Grille frame, Broken, Replace



Bumper F, Scratch(es), Repair and paint (complete)



Number plate F, Deformed / Strained, Repair/replace (lump sum)



Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Bumper corner RR, Scratch(es), Repair and paint (complete)



Reflector, Unclassped, Replace



Bumper R, Scratch(es), Repair and paint (complete)



Tyres, No damage, Check





Bodywork, Glue residues, Remove lettering



Datos del vehículo

Marca

Modelo

Versión

Matrícula

VIN

Histórico

Fecha	Descripción	Kilómetros	Taller

Datos del vehículo

Marca

Modelo

Versión

Matrícula

VIN

Histórico

Fecha	Descripción	Kilómetros	Taller