


Vehicle data sheet

Vehicle details

Vin	VF1RHN00071862120	Pla.	J	Distance km	17458	Date immat	28/03/2024
Location				Appr. date	04/05/2026		
Model	AUSTRAL	Color	Grigio scisto	Enamel type	Metall double		





Documents	
Registration certificate	✓
Green card	✓
Insurance certificate	✓
Service booklet	✓
Owner manual	✓
Key code card	✓
Second key	✓
Master key	✓

Vehicle info	
Battery charged / compliant	✓
Fuel level	1/4
Interior clean/acceptable	✓
Interior material/colour	Fabric / Dark
Exterior clean/acceptable	✗
Plates compliant/readable	✓

Accessories	
Remote controls (Working)	✓
Smoker kit	✗
Radio/nav antenna	✓
Audio unit (Working)	✓
Navigator (Working)	✓
Map support	PRELOADED
Floor mats	✓

Equipment	
Tool kit	✓
Cylinder	✗
Locking wheel bolt	✓
First aid kit	✓
Warning triangle	✓
Hat rack	✓
Luggage compartment mat	✓

✓ - Elemento presente
 ✗ - Elemento assente
 ? - Elemento presente ma non verificabile

Tires				
Right front tire	BF Goodrich	205/55/19	All-season	6 mm
Left front tire	BF Goodrich	205/55/19	All-season	4 mm
Right rear tire	BF Goodrich	205/55/19	All-season	6 mm
Left rear tire	BF Goodrich	205/55/19	All-season	5 mm
Spare wheel				

Damage detail

Component	#PRM# Left front wheel damaged	Side	
Component	#PRM# Right front wheel damaged	Side	
Component	#PRM# Left rear wheel damaged	Side	
Component	#PRM# Right rear wheel damaged	Side	
Component	#PRM# Shell rearview mirror ext. black	Side	Right
Component	Windscreen	Side	

Descriptions legend

D.E.: Defect of execution on previously repaired area

PRIMER: Component provided already pre trattato for the vernicia **PRM**: Normal wear